

Accident Date BETWEEN '01-Jul-2007' AND '30-Jun-2012'

Accident Reference: 49070      Slight      Junc Exchange St/Queens Rd East to Junc Surrogate St      Accident 71 of 119

Date & time.....Thursday 23/10/2008 10:45	Speed limit.....30 Mph
Grid reference.....604950/295431	Road type.....One Way St
District.....Breckland	Junction detail.....Crossroads
Primary road.....B1077	Junction control.....Give way sign or uncontrolled
Secondary road.....B1077	Special conditions...None
Weather.....Fine	Carriageway hazards..None
Lighting.....Daylight	Number of vehicles...2
Crossing(human).....No Human control within 50m	Number of casualties.1
Crossing(physical)..No crossing facility within 50m	Surface.....Dry

**Did a police officer attend?**  
Yes

**Accident Description**

Veh 1 (Car), Slowing or Stopping from West to South; Veh 2 (M/Cycle over 500Cc), Going ahead Other from Northeast to South. Collision Diagram Info: Collision with Vehicle from left

**2 Vehicles**

Vehicle number.....1	First impact.....Front
Other vehicle.....2	Hit object in c'way..None
Vehicle class.....Car	Hit object off c'way.None
Junction location..Mid junction	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Male
Direction.....West South	Driver age.....43
Manoeuvres.....Stopping	
Skidding.....No	Hit and Run.....No
Left c'way.....Did not leave c'way	Breath test.....Negative
Towing.....No	Journey purpose.....
Foreign vehicle....Not foreign	

Vehicle number.....2	First impact.....Offside
Other vehicle.....1	Hit object in c'way..None
Vehicle class.....M/cycle > 500cc	Hit object off c'way.None
Junction location..Mid junction	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Male
Direction.....North east South	Driver age.....50
Manoeuvres.....Going ahead other	
Skidding.....No	Hit and Run.....No
Left c'way.....Did not leave c'way	Breath test.....Not requested
Towing.....No	Journey purpose.....
Foreign vehicle....Not foreign	

**1 Casualty**

Casualty number.....1	Car passenger.....Not a passenger
Casualty class.....Driver or Rider	PSV passenger.....Not a passenger
Gender.....Male	Seat belt usage.....
Age.....50	School pupil.....Other
	School .....
Severity.....Slight	Pedestrian location..
Vehicle no.....2	Pedestrian movement..
Ped Direction.....	Roadworker injured...

Accident Date BETWEEN '01-Jul-2007' AND '30-Jun-2012'

Accident Reference: 0058744      Slight      Station Road First Road: B1077, Second Road: B1077      Accident 72 of 119

Date & time.....Friday 24/09/2010 11:45	Speed limit.....30 Mph
Grid reference.....604955/295245	Road type.....One Way St
District.....Breckland	Junction detail.....T or Staggered junction
Primary road.....B1077	Junction control.....Give way sign or uncontrolled
Secondary road.....B1077	Special conditions...None
Weather.....Rain Wind	Carriageway hazards..None
Lighting.....Daylight	Number of vehicles...1
Crossing(human)....No Human control within 50m	Number of casualties.1
Crossing(physical)..No crossing facility within 50m	Surface.....Wet

**Did a police officer attend?**  
Yes

**Accident Description**

Veh 1 (Car), Going ahead right Hand Bend from West to Southeast.

**1 Vehicle**

Vehicle number.....1	First impact.....Front
Other vehicle.....0	Hit object in c'way..None
Vehicle class.....Car	Hit object off c'way.None
Junction location...Cleared junction or parked at junctio	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Male
Direction.....West South east	Driver age.....-1
Manoeuvres.....Going ahead right hand bend	
Skidding.....No	Hit and Run.....No
Left c'way.....Did not leave c'way	Breath test.....Not requested
Towing.....No	Journey purpose.....Journey as part of work
Foreign vehicle.....Not foreign	

**1 Casualty**

Casualty number.....1	Car passenger.....Not a passenger
Casualty class.....Pedestrian	PSV passenger.....Not a passenger
Gender.....Female	Seat belt usage.....
Age.....74	School pupil.....Other
	School .....
Severity.....Slight	Pedestrian location..In carriageway, crossing elsewhere
Vehicle no.....1	Pedestrian movement..Crossing from driver's nearside
Ped Direction.....Northeast bound	Roadworker injured...Not applicable

Accident Date BETWEEN '01-Jul-2007' AND '30-Jun-2012'

Accident Reference: 0056408      Slight      Church Street First Road: B1077, Second Road: C139      Accident 73 of 119

Date & time.....Wednesday 28/04/2010 12:45	Speed limit.....30 Mph
Grid reference.....604963/295420	Road type.....Single c'way
District.....Breckland	Junction detail.....Crossroads
Primary road.....B1077	Junction control.....Give way sign or uncontrolled
Secondary road.....C139	Special conditions...None
Weather.....Fine	Carriageway hazards..None
Lighting.....Daylight	Number of vehicles...2
Crossing(human)....No Human control within 50m	Number of casualties.1
Crossing(physical)..No crossing facility within 50m	Surface.....Dry

**Did a police officer attend?**  
Yes

**Accident Description**

Veh 1 (Car), Going ahead Other from South to North; Veh 2 (M/Cycle upto 125Cc), Going ahead Other from East to North.

**2 Vehicles**

Vehicle number.....1	First impact.....Nearside
Other vehicle.....2	Hit object in c'way..None
Vehicle class.....Car	Hit object off c'way.None
Junction location..Mid junction	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Male
Direction.....South North	Driver age.....84
Manoeuvres.....Going ahead other	
Skidding.....No	Hit and Run.....No
Left c'way.....Did not leave c'way	Breath test.....Negative
Towing.....No	Journey purpose.....Other
Foreign vehicle....Not foreign	

Vehicle number.....2	First impact.....Front
Other vehicle.....1	Hit object in c'way..None
Vehicle class.....M/cycle 50 - 125cc	Hit object off c'way.None
Junction location..Mid junction	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Female
Direction.....East North	Driver age.....20
Manoeuvres.....Going ahead other	
Skidding.....No	Hit and Run.....No
Left c'way.....Did not leave c'way	Breath test.....Negative
Towing.....No	Journey purpose.....Other
Foreign vehicle....Not foreign	

**1 Casualty**

Casualty number.....1	Car passenger.....Not a passenger
Casualty class.....Passenger	PSV passenger.....Not a passenger
Gender.....Female	Seat belt usage.....
Age.....20	School pupil.....Other
	School .....
Severity.....Slight	Pedestrian location..
Vehicle no.....2	Pedestrian movement..
Ped Direction.....	Roadworker injured...

Accident Date BETWEEN '01-Jul-2007' AND '30-Jun-2012'

Accident Reference: 0057219      Slight      Church Street First Road: B1077, Second Road: C139      Accident 74 of 119

Date & time.....	Tuesday 06/07/2010 11:30	Speed limit.....	30 Mph
Grid reference.....	604963/295420	Road type.....	One Way St
District.....	Breckland	Junction detail.....	Junction - more than 4 arms
Primary road.....	B1077	Junction control.....	Give way sign or uncontrolled
Secondary road.....	C139	Special conditions...	None
Weather.....	Fine	Carriageway hazards..	None
Lighting.....	Daylight	Number of vehicles...	2
Crossing(human)....	No Human control within 50m	Number of casualties..	1
Crossing(physical)..	No crossing facility within 50m	Surface.....	Dry

**Did a police officer attend?**  
No - reported over the counter

**Accident Description**

Veh 1 (Goods Vehicle >= 7.5T), turning left from East to South; Veh 2 (Car), Going ahead right Hand Bend from West to South.

**2 Vehicles**

Vehicle number.....	1	First impact.....	Front
Other vehicle.....	2	Hit object in c'way..	None
Vehicle class.....	Goods > 7.5t	Hit object off c'way..	None
Junction location...	Entering main road	Parts damaged.....	/ /
Restricted location..	On main carriageway	Driver gender.....	Not known
Direction.....	East South	Driver age.....	-1
Manoeuvres.....	Turning left	Hit and Run.....	Yes
Skidding.....	No	Breath test.....	Not contacted
Left c'way.....	Did not leave c'way	Journey purpose.....	Journey as part of work
Towing.....	No		
Foreign vehicle.....	Not foreign		

Vehicle number.....	2	First impact.....	Nearside
Other vehicle.....	1	Hit object in c'way..	None
Vehicle class.....	Car	Hit object off c'way..	None
Junction location...	Mid junction	Parts damaged.....	/ /
Restricted location..	On main carriageway	Driver gender.....	Female
Direction.....	West South	Driver age.....	20
Manoeuvres.....	Going ahead right hand bend	Hit and Run.....	No
Skidding.....	No	Breath test.....	Not contacted
Left c'way.....	Did not leave c'way	Journey purpose.....	Other
Towing.....	No		
Foreign vehicle.....	Not foreign		

**1 Casualty**

Casualty number.....	1	Car passenger.....	Not a passenger
Casualty class.....	Driver or Rider	PSV passenger.....	Not a passenger
Gender.....	Female	Seat belt usage.....	
Age.....	20	School pupil.....	Other
Severity.....	Slight	School .....	
Vehicle no.....	2	Pedestrian location..	
Ped Direction.....		Pedestrian movement..	
		Roadworker injured...	

Accident Date BETWEEN '01-Jul-2007' AND '30-Jun-2012'

Accident Reference: 0058379      Slight      Church Street First Road: B1077, Second Road: C139      Accident 75 of 119

Date & time.....Sunday 03/10/2010 18:00	Speed limit.....30 Mph
Grid reference.....604963/295420	Road type.....Single c'way
District.....Breckland	Junction detail.....Crossroads
Primary road.....B1077	Junction control.....Give way sign or uncontrolled
Secondary road.....C139	Special conditions...None
Weather.....Rain	Carriageway hazards..None
Lighting.....Dark/lights lit	Number of vehicles...2
Crossing(human)....No Human control within 50m	Number of casualties.1
Crossing(physical)..No crossing facility within 50m	Surface.....Wet

**Did a police officer attend?**  
Yes

**Accident Description**

Veh 1 (Car), Going ahead Other from West to East; Veh 2 (Car), Going ahead Other from Northeast to South.

**2 Vehicles**

Vehicle number.....1	First impact.....Front
Other vehicle.....2	Hit object in c'way..None
Vehicle class.....Car	Hit object off c'way.Other permanent object
Junction location...Entering main road	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Female
Direction.....West East	Driver age.....58
Manoeuvres.....Going ahead other	
Skidding.....No	Hit and Run.....No
Left c'way.....Left c'way Offside	Breath test.....Negative
Towing.....No	Journey purpose.....Journey as part of work
Foreign vehicle....Not foreign	

Vehicle number.....2	First impact.....Offside
Other vehicle.....1	Hit object in c'way..None
Vehicle class.....Car	Hit object off c'way.None
Junction location...Mid junction	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Male
Direction.....North east South	Driver age.....27
Manoeuvres.....Going ahead other	
Skidding.....No	Hit and Run.....No
Left c'way.....Did not leave c'way	Breath test.....Negative
Towing.....No	Journey purpose.....Other
Foreign vehicle....Not foreign	

**1 Casualty**

Casualty number.....1	Car passenger.....Not a passenger
Casualty class.....Driver or Rider	PSV passenger.....Not a passenger
Gender.....Female	Seat belt usage.....
Age.....58	School pupil.....Other
	School .....
Severity.....Slight	Pedestrian location..
Vehicle no.....1	Pedestrian movement..
Ped Direction.....	Roadworker injured...

Accident Date BETWEEN '01-Jul-2007' AND '30-Jun-2012'

Accident Reference:0063164	Slight	Surrogate Street First Road: B1077, Second Road: C139	Accident 76 of 119
Date & time.....Friday 21/10/2011 05:35		Speed limit.....30 Mph	
Grid reference.....604964/295401		Road type.....Single c'way	
District.....Breckland		Junction detail.....Crossroads	
Primary road.....B1077		Junction control.....Give way sign or uncontrolled	
Secondary road.....C139		Special conditions...None	
Weather.....Fine		Carriageway hazards..None	
Lighting.....Dark/lights lit		Number of vehicles...1	
Crossing(human)....No Human control within 50m		Number of casualties.2	
Crossing(physical)..Central Refuge only		Surface.....Dry	

**Did a police officer attend?**  
Yes

**Accident Description**

Veh 1 (Car), Going ahead Other from East to West.

**1 Vehicle**

Vehicle number.....1	First impact.....Front
Other vehicle.....0	Hit object in c'way..None
Vehicle class.....Car	Hit object off c'way.Road sign or signal
Junction location...Mid junction	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Female
Direction.....East West	Driver age.....39
Manoeuvres.....Going ahead other	
Skidding.....No	Hit and Run.....No
Left c'way.....Left c'way Offside	Breath test.....Negative
Towing.....No	Journey purpose.....Commuting to/from work
Foreign vehicle....Not foreign	

**2 Casualties**

Casualty number.....1	Car passenger.....Not a passenger
Casualty class.....Driver or Rider	PSV passenger.....Not a passenger
Gender.....Female	Seat belt usage.....
Age.....39	School pupil.....Other
	School .....
Severity.....Slight	Pedestrian location..
Vehicle no.....1	Pedestrian movement..
Ped Direction.....	Roadworker injured...
Casualty number.....2	Car passenger.....Rear seat passenger
Casualty class.....Passenger	PSV passenger.....Not a passenger
Gender.....Female	Seat belt usage.....
Age.....56	School pupil.....Other
	School .....
Severity.....Slight	Pedestrian location..
Vehicle no.....1	Pedestrian movement..
Ped Direction.....	Roadworker injured...



Accident Date BETWEEN '01-Jul-2007' AND '30-Jun-2012'

Accident Reference: T100018      Slight      Surrogate Street First Road: B1077      Accident 78 of 119

Date & time.....Monday 15/02/2010 15:33	Speed limit.....30 Mph
Grid reference.....604970/295372	Road type.....One Way St
District.....Breckland	Junction detail.....Not at or within 20m of junction
Primary road.....B1077	Junction control.....
Secondary road.....	Special conditions...None
Weather.....Fine	Carriageway hazards..None
Lighting.....Daylight	Number of vehicles...1
Crossing(human)....No Human control within 50m	Number of casualties.1
Crossing(physical)..No crossing facility within 50m	Surface.....Dry

**Did a police officer attend?**  
Yes

**Accident Description**

Veh 1 (M/Cycle over 500Cc), Going ahead Other from North to South. Collision Diagram Info: Crossing Road from Offside

**1 Vehicle**

Vehicle number.....1	First impact.....Front
Other vehicle.....0	Hit object in c'way..None
Vehicle class.....M/cycle > 500cc	Hit object off c'way.None
Junction location...Not at junction	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Male
Direction.....North South	Driver age.....21
Manoeuvres.....Going ahead other	
Skidding.....Overturned	Hit and Run.....No
Left c'way.....Did not leave c'way	Breath test.....Negative
Towing.....No	Journey purpose.....Commuting to/from work
Foreign vehicle.....Not foreign	

**1 Casualty**

Casualty number.....1	Car passenger.....Not a passenger
Casualty class.....Pedestrian	PSV passenger.....Not a passenger
Gender.....Male	Seat belt usage.....
Age.....14	School pupil.....Yes on way to or from school
	School .....
Severity.....Slight	Pedestrian location..In carriageway, crossing elsewhere
Vehicle no.....1	Pedestrian movement..Crossing from driver's offside
Ped Direction.....East bound	Roadworker injured...Not applicable

Accident Date BETWEEN '01-Jul-2007' AND '30-Jun-2012'

Accident Reference: T070301      Slight      Junc U33092 Whitehouse La to Junc Connaught Rd      Accident 79 of 119

Date & time.....Saturday 08/12/2007 16:30	Speed limit.....30 Mph
Grid reference.....604983/295212	Road type.....Single c'way
District.....Breckland	Junction detail.....Not at or within 20m of junction
Primary road.....B1077	Junction control.....
Secondary road.....	Special conditions...None
Weather.....Rain Wind	Carriageway hazards..None
Lighting.....Dark/lights lit	Number of vehicles...2
Crossing(human)....No Human control within 50m	Number of casualties.1
Crossing(physical)..No crossing facility within 50m	Surface.....Wet

**Did a police officer attend?**  
Yes

**Accident Description**

Veh 1 (Car), Going ahead left Hand Bend from Northwest to Southeast; Veh 2 (Minibus), Parked from Parked to Parked. Collision Diagram Info: Collision with Parked Vehicle on Nearside

**2 Vehicles**

Vehicle number.....1	First impact.....Front
Other vehicle.....2	Hit object in c'way..Parked vehicle unlit
Vehicle class.....Car	Hit object off c'way..None
Junction location...Not at junction	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Male
Direction.....North west South east	Driver age.....68
Manoeuvres.....Going ahead left hand bend	
Skidding.....No	Hit and Run.....No
Left c'way.....Did not leave c'way	Breath test.....Negative
Towing.....No	Journey purpose.....
Foreign vehicle....Not foreign	

Vehicle number.....2	First impact.....Back
Other vehicle.....1	Hit object in c'way..None
Vehicle class.....Minibus	Hit object off c'way..None
Junction location...Not at junction	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Male
Direction.....Parked Parked	Driver age.....56
Manoeuvres.....Parked	
Skidding.....No	Hit and Run.....No
Left c'way.....Did not leave c'way	Breath test.....Negative
Towing.....No	Journey purpose.....
Foreign vehicle....Not foreign	

**1 Casualty**

Casualty number.....1	Car passenger.....Rear seat passenger
Casualty class.....Passenger	PSV passenger.....Not a passenger
Gender.....Male	Seat belt usage.....
Age.....62	School pupil.....Other
	School .....
Severity.....Slight	Pedestrian location..
Vehicle no.....2	Pedestrian movement..
Ped Direction.....	Roadworker injured...

Accident Date BETWEEN '01-Jul-2007' AND '30-Jun-2012'

Accident Reference:0063558      Serious      Station Road First Road: B1077, Second Road: B1077      Accident 80 of 119

Date & time.....Monday 21/11/2011 10:05	Speed limit.....30 Mph
Grid reference.....604983/295212	Road type.....Single c'way
District.....Breckland	Junction detail.....Junction - more than 4 arms
Primary road.....B1077	Junction control.....Give way sign or uncontrolled
Secondary road.....B1077	Special conditions...Roadworks
Weather.....Other	Carriageway hazards..None
Lighting.....Daylight	Number of vehicles...1
Crossing(human).....No Human control within 50m	Number of casualties.1
Crossing(physical)..No crossing facility within 50m	Surface.....Wet

**Did a police officer attend?**  
Yes

**Accident Description**

Veh 1 (Goods Vehicle Between 3.5T and 7.5T), Moving off from North to Southeast.

**1 Vehicle**

Vehicle number.....1	First impact.....Front
Other vehicle.....0	Hit object in c'way..None
Vehicle class.....Goods 3.5 - 7.5t	Hit object off c'way.None
Junction location...Cleared junction or parked at junctio	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Male
Direction.....North South east	Driver age.....37
Manoeuvres.....Starting	
Skidding.....No	Hit and Run.....No
Left c'way.....Did not leave c'way	Breath test.....Negative
Towing.....No	Journey purpose.....Journey as part of work
Foreign vehicle.....Not foreign	

**1 Casualty**

Casualty number.....1	Car passenger.....Not a passenger
Casualty class.....Pedestrian	PSV passenger.....Not a passenger
Gender.....Male	Seat belt usage.....
Age.....37	School pupil.....Other
	School .....
Severity.....Serious	Pedestrian location..In carriageway, crossing elsewhere
Vehicle no.....1	Pedestrian movement..Crossing from driver's nearside
Ped Direction.....West bound	Roadworker injured...Not applicable

Accident Date BETWEEN '01-Jul-2007' AND '30-Jun-2012'

Accident Reference: 0057385      Slight      Norwich Road First Road: B1077      Accident 81 of 119

Date & time.....Tuesday 13/07/2010 15:30	Speed limit.....30 Mph
Grid reference.....605044/295526	Road type.....Single c'way
District.....Breckland	Junction detail.....Not at or within 20m of junction
Primary road.....B1077	Junction control.....
Secondary road.....	Special conditions...None
Weather.....Fine	Carriageway hazards..None
Lighting.....Daylight	Number of vehicles...1
Crossing(human).....No Human control within 50m	Number of casualties..1
Crossing(physical)..No crossing facility within 50m	Surface.....Dry

**Did a police officer attend?**  
No - reported over the counter

**Accident Description**

Veh 1 (Car), Going ahead Other from Southwest to Northeast.

**1 Vehicle**

Vehicle number.....1	First impact.....Offside
Other vehicle.....0	Hit object in c'way..None
Vehicle class.....Car	Hit object off c'way..None
Junction location...Not at junction	Parts damaged..... / /
Restricted location..On main carriageway	Driver gender.....Male
Direction.....South west North east	Driver age.....-1
Manoeuvres.....Going ahead other	
Skidding.....No	Hit and Run.....Yes
Left c'way.....Did not leave c'way	Breath test.....Not contacted
Towing.....No	Journey purpose.....Other
Foreign vehicle.....Not foreign	

**1 Casualty**

Casualty number.....1	Car passenger.....Not a passenger
Casualty class.....Pedestrian	PSV passenger.....Not a passenger
Gender.....Female	Seat belt usage.....
Age.....10	School pupil.....Other
	School .....
Severity.....Slight	Pedestrian location..In carriageway, crossing elsewhere
Vehicle no.....1	Pedestrian movement..Crossing from driver's offside
Ped Direction.....Northwest bound	Roadworker injured...Not applicable

Accident Date BETWEEN '01-Jul-2007' AND '30-Jun-2012'

Accident Reference: 0052026      Slight      Station Road First Road: B1077      Accident 82 of 119

Date & time.....Friday 29/05/2009 08:50	Speed limit.....30 Mph
Grid reference.....605135/295014	Road type.....Single c'way
District.....Breckland	Junction detail.....Other Junction
Primary road.....B1077	Junction control.....Give way sign or uncontrolled
Secondary road.....	Special conditions...None
Weather.....Fine	Carriageway hazards..None
Lighting.....Daylight	Number of vehicles...2
Crossing(human)....No Human control within 50m	Number of casualties..2
Crossing(physical)..No crossing facility within 50m	Surface.....Dry

**Did a police officer attend?**  
Yes

**Accident Description**

Veh 1 (Car), Going ahead Other from Southeast to Northwest; Veh 2 (Goods Vehicle <= 3.5T), Going ahead Other from Southeast to Northwest. Collision Diagram Info: Tail End Collision

**2 Vehicles**

Vehicle number.....1	First impact.....Front
Other vehicle.....2	Hit object in c'way..None
Vehicle class.....Car	Hit object off c'way.None
Junction location..Mid junction	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Male
Direction.....South east North west	Driver age.....17
Manoeuvres.....Going ahead other	
Skidding.....No	Hit and Run.....No
Left c'way.....Did not leave c'way	Breath test.....Negative
Towing.....No	Journey purpose.....Commuting to/from work
Foreign vehicle....Not foreign	

Vehicle number.....2	First impact.....Back
Other vehicle.....1	Hit object in c'way..None
Vehicle class.....Van/Goods < 3.5t	Hit object off c'way.None
Junction location..Mid junction	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Male
Direction.....South east North west	Driver age.....48
Manoeuvres.....Going ahead other	
Skidding.....No	Hit and Run.....No
Left c'way.....Did not leave c'way	Breath test.....Negative
Towing.....No	Journey purpose.....Journey as part of work
Foreign vehicle....Not foreign	

**2 Casualties**

Casualty number.....1	Car passenger.....Not a passenger
Casualty class.....Driver or Rider	PSV passenger.....Not a passenger
Gender.....Male	Seat belt usage.....
Age.....17	School pupil.....Other
	School .....
Severity.....Slight	Pedestrian location..
Vehicle no.....1	Pedestrian movement..
Ped Direction.....	Roadworker injured...

Casualty number.....2	Car passenger.....Not a passenger
Casualty class.....Driver or Rider	PSV passenger.....Not a passenger
Gender.....Male	Seat belt usage.....
Age.....48	School pupil.....Other
	School .....
Severity.....Slight	Pedestrian location..
Vehicle no.....2	Pedestrian movement..
Ped Direction.....	Roadworker injured...

Accident Date BETWEEN '01-Jul-2007' AND '30-Jun-2012'

Accident Reference: 0065543      Slight      First Road: B1077      Accident 83 of 119

Date & time.....Saturday 28/04/2012 06:30	Speed limit.....30 Mph
Grid reference.....605240/295820	Road type.....Single c'way
District.....Breckland	Junction detail.....Not at or within 20m of junction
Primary road.....B1077	Junction control.....
Secondary road.....	Special conditions...None
Weather.....Rain	Carriageway hazards..None
Lighting.....Daylight	Number of vehicles...2
Crossing(human).....No Human control within 50m	Number of casualties.1
Crossing(physical)..No crossing facility within 50m	Surface.....Wet

**Did a police officer attend?**  
Yes

**Accident Description**

Veh 1 (Car), Going ahead right Hand Bend from Southwest to Northeast; Veh 2 (Car), Going ahead left Hand Bend from Northeast to Southwest.

**2 Vehicles**

Vehicle number.....1	First impact.....Front
Other vehicle.....2	Hit object in c'way..None
Vehicle class.....Car	Hit object off c'way.None
Junction location...Not at junction	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Male
Direction.....South west North east	Driver age.....33
Manoeuvres.....Going ahead right hand bend	
Skidding.....Yes	Hit and Run.....No
Left c'way.....Did not leave c'way	Breath test.....Negative
Towing.....No	Journey purpose.....Other
Foreign vehicle....Not foreign	

Vehicle number.....2	First impact.....Front
Other vehicle.....1	Hit object in c'way..None
Vehicle class.....Car	Hit object off c'way.None
Junction location...Not at junction	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Male
Direction.....North east South west	Driver age.....48
Manoeuvres.....Going ahead left hand bend	
Skidding.....Yes	Hit and Run.....No
Left c'way.....Did not leave c'way	Breath test.....Not requested
Towing.....No	Journey purpose.....Journey as part of work
Foreign vehicle....Not foreign	

**1 Casualty**

Casualty number.....1	Car passenger.....Not a passenger
Casualty class.....Driver or Rider	PSV passenger.....Not a passenger
Gender.....Male	Seat belt usage.....
Age.....48	School pupil.....Other
	School .....
Severity.....Slight	Pedestrian location..
Vehicle no.....2	Pedestrian movement..
Ped Direction.....	Roadworker injured...

Accident Date BETWEEN '01-Jul-2007' AND '30-Jun-2012'

**Accident Reference:**0063127      Slight      Buckenham Road First Road: B1077, Second Road: 33127      Accident 84 of 119

Date & time.....Wednesday 19/10/2011 15:05	Speed limit.....60 Mph
Grid reference.....605507/294478	Road type.....Single c'way
District.....Breckland	Junction detail.....T or Staggered junction
Primary road.....B1077	Junction control.....Give way sign or uncontrolled
Secondary road.....U33127	Special conditions...None
Weather.....Fine	Carriageway hazards..None
Lighting.....Daylight	Number of vehicles...2
Crossing(human).....No Human control within 50m	Number of casualties.1
Crossing(physical)..No crossing facility within 50m	Surface.....Dry

**Did a police officer attend?**  
Yes

**Accident Description**

Veh 1 (Car), Going ahead Other from North to South; Veh 2 (M/Cycle over 500Cc), Slowing or Stopping from North to South.

**2 Vehicles**

Vehicle number.....1	First impact.....Front
Other vehicle.....2	Hit object in c'way..None
Vehicle class.....Car	Hit object off c'way.None
Junction location..Mid junction	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Male
Direction.....North South	Driver age.....18
Manoeuvres.....Going ahead other	
Skidding.....No	Hit and Run.....No
Left c'way.....Did not leave c'way	Breath test.....Negative
Towing.....No	Journey purpose.....Other
Foreign vehicle.....Not foreign	

Vehicle number.....2	First impact.....Back
Other vehicle.....1	Hit object in c'way..None
Vehicle class.....M/cycle > 500cc	Hit object off c'way.None
Junction location..Mid junction	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Male
Direction.....North South	Driver age.....72
Manoeuvres.....Stopping	
Skidding.....No	Hit and Run.....No
Left c'way.....Did not leave c'way	Breath test.....Negative
Towing.....No	Journey purpose.....Other
Foreign vehicle.....Not foreign	

**1 Casualty**

Casualty number.....1	Car passenger.....Not a passenger
Casualty class.....Driver or Rider	PSV passenger.....Not a passenger
Gender.....Male	Seat belt usage.....
Age.....72	School pupil.....Other
	School .....
Severity.....Slight	Pedestrian location..
Vehicle no.....2	Pedestrian movement..
Ped Direction.....	Roadworker injured...



Accident Reference: 42923                      Slight                      Accident 86 of 119

Date & time.....Monday 27/08/2007 13:03	Speed limit.....60 Mph
Grid reference.....605552/295027	Road type.....Single c'way
District.....Breckland	Junction detail.....Not at or within 20m of junction
Primary road.....U33092	Junction control.....
Secondary road.....	Special conditions...None
Weather.....Fine	Carriageway hazards..None
Lighting.....Daylight	Number of vehicles...2
Crossing(human)....No Human control within 50m	Number of casualties.1
Crossing(physical)..No crossing facility within 50m	Surface.....Dry

**Did a police officer attend?**  
Yes

**Accident Description**

Veh 1 (Car), Going ahead left Hand Bend from Northeast to Southwest; Veh 2 (Car), Going ahead right Hand Bend from Southwest to Northeast. Collision Diagram Info: Head on Collision

**2 Vehicles**

Vehicle number.....1	First impact.....Front
Other vehicle.....2	Hit object in c'way..None
Vehicle class.....Car	Hit object off c'way.None
Junction location...Not at junction	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Male
Direction.....North east South west	Driver age.....21
Manoeuvres.....Going ahead left hand bend	
Skidding.....No	Hit and Run.....No
Left c'way.....Did not leave c'way	Breath test.....Negative
Towing.....No	Journey purpose.....
Foreign vehicle....Not foreign	

Vehicle number.....2	First impact.....Front
Other vehicle.....1	Hit object in c'way..None
Vehicle class.....Car	Hit object off c'way.None
Junction location...Not at junction	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Male
Direction.....South west North east	Driver age.....24
Manoeuvres.....Going ahead right hand bend	
Skidding.....Yes	Hit and Run.....No
Left c'way.....Did not leave c'way	Breath test.....Negative
Towing.....No	Journey purpose.....
Foreign vehicle....Not foreign	

**1 Casualty**

Casualty number.....1	Car passenger.....Rear seat passenger
Casualty class.....Passenger	PSV passenger.....Not a passenger
Gender.....Male	Seat belt usage.....
Age.....29	School pupil.....Other
	School .....
Severity.....Slight	Pedestrian location..
Vehicle no.....2	Pedestrian movement..
Ped Direction.....	Roadworker injured...

Accident Date BETWEEN '01-Jul-2007' AND '30-Jun-2012'

**Accident Reference:** 48759      Slight      40/60 S1 South Southern Ppy Bdy Bethany to 10M South      Accident 87 of 119  
 Junc U33090

Date & time.....Monday 29/09/2008 16:10	Speed limit.....60 Mph
Grid reference.....605573/294341	Road type.....Single c'way
District.....Breckland	Junction detail.....Not at or within 20m of junction
Primary road.....B1077	Junction control.....
Secondary road.....	Special conditions...None
Weather.....Fine	Carriageway hazards..None
Lighting.....Daylight	Number of vehicles...2
Crossing(human).....No Human control within 50m	Number of casualties.1
Crossing(physical)..No crossing facility within 50m	Surface.....Dry

**Did a police officer attend?**  
 Yes

**Accident Description**

Veh 1 (Car), Overtaking Moving Veh on its Offside from North to South; Veh 2 (Pedal Cycle), Going ahead Other from North to South. Collision Diagram Info: Overtaking on Offside

**2 Vehicles**

Vehicle number.....1	First impact.....Nearside
Other vehicle.....2	Hit object in c'way..None
Vehicle class.....Car	Hit object off c'way.None
Junction location...Not at junction	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Not known
Direction.....North South	Driver age.....-1
Manoeuvres.....O/T moving vehicle on its O/S	
Skidding.....No	Hit and Run.....No
Left c'way.....Did not leave c'way	Breath test.....Not contacted
Towing.....No	Journey purpose.....
Foreign vehicle.....Not foreign	

Vehicle number.....2	First impact.....Offside
Other vehicle.....1	Hit object in c'way..None
Vehicle class.....Pedal Cycle	Hit object off c'way.None
Junction location...Not at junction	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Female
Direction.....North South	Driver age.....15
Manoeuvres.....Going ahead other	
Skidding.....No	Hit and Run.....No
Left c'way.....Did not leave c'way	Breath test.....Not applicable
Towing.....No	Journey purpose.....
Foreign vehicle.....Not foreign	

**1 Casualty**

Casualty number.....1	Car passenger.....Not a passenger
Casualty class.....Driver or Rider	PSV passenger.....Not a passenger
Gender.....Female	Seat belt usage.....
Age.....15	School pupil.....Other
	School .....
Severity.....Slight	Pedestrian location..
Vehicle no.....2	Pedestrian movement..
Ped Direction.....	Roadworker injured...

Accident Date BETWEEN '01-Jul-2007' AND '30-Jun-2012'

Accident Reference: 0063465      Slight      Buckenham Road First Road: B1077      Accident 88 of 119

Date & time.....Thursday 17/11/2011 08:27	Speed limit.....60 Mph
Grid reference.....605585/294312	Road type.....Single c'way
District.....Breckland	Junction detail.....Using private drive or entrance
Primary road.....B1077	Junction control.....Give way sign or uncontrolled
Secondary road.....	Special conditions...None
Weather.....Fog Mist	Carriageway hazards..None
Lighting.....Daylight	Number of vehicles...2
Crossing(human).....No Human control within 50m	Number of casualties.1
Crossing(physical)..No crossing facility within 50m	Surface.....Wet

**Did a police officer attend?**  
Yes

**Accident Description**

Veh 1 (Car), turning left from Southwest to Northwest; Veh 2 (Goods Vehicle >= 7.5T), Going ahead Other from Northwest to Southeast.

**2 Vehicles**

Vehicle number.....1	First impact.....Front
Other vehicle.....2	Hit object in c'way..None
Vehicle class.....Car	Hit object off c'way.None
Junction location...Entering main road	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Male
Direction.....South west North west	Driver age.....28
Manoeuvres.....Turning left	
Skidding.....No	Hit and Run.....No
Left c'way.....Did not leave c'way	Breath test.....Negative
Towing.....No	Journey purpose.....Journey as part of work
Foreign vehicle.....Not foreign	

Vehicle number.....2	First impact.....Front
Other vehicle.....1	Hit object in c'way..None
Vehicle class.....Goods > 7.5t	Hit object off c'way.None
Junction location...Mid junction	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Male
Direction.....North west South east	Driver age.....64
Manoeuvres.....Going ahead other	
Skidding.....No	Hit and Run.....No
Left c'way.....Did not leave c'way	Breath test.....Negative
Towing.....Articulated veh.	Journey purpose.....Journey as part of work
Foreign vehicle.....Not foreign	

**1 Casualty**

Casualty number.....1	Car passenger.....Not a passenger
Casualty class.....Driver or Rider	PSV passenger.....Not a passenger
Gender.....Male	Seat belt usage.....
Age.....28	School pupil.....Other
	School .....
Severity.....Slight	Pedestrian location..
Vehicle no.....1	Pedestrian movement..
Ped Direction.....	Roadworker injured...

Accident Date BETWEEN '01-Jul-2007' AND '30-Jun-2012'

**Accident Reference:**0057567      Slight      Buckenham Road First Road: B1077, Second Road: 33089      Accident 89 of 119

Date & time.....Sunday 11/07/2010 13:15	Speed limit.....60 Mph
Grid reference.....605731/294042	Road type.....Single c'way
District.....Breckland	Junction detail.....T or Staggered junction
Primary road.....B1077	Junction control.....Give way sign or uncontrolled
Secondary road.....U33089	Special conditions...Oil or diesel
Weather.....Fine	Carriageway hazards..None
Lighting.....Daylight	Number of vehicles...1
Crossing(human).....No Human control within 50m	Number of casualties..1
Crossing(physical)..No crossing facility within 50m	Surface.....Dry

**Did a police officer attend?**  
Yes

**Accident Description**

Veh 1 (M/Cycle over 500Cc), Going ahead left Hand Bend from South to Northwest.

**1 Vehicle**

Vehicle number.....1	First impact.....Nearside
Other vehicle.....0	Hit object in c'way..None
Vehicle class.....M/cycle > 500cc	Hit object off c'way.Other permanent object
Junction location...Mid junction	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Female
Direction.....South North west	Driver age.....34
Manoeuvres.....Going ahead left hand bend	Hit and Run.....No
Skidding.....Yes & Overturned	Breath test.....Negative
Left c'way.....Left c'way Offside	Journey purpose.....Other
Towing.....No	
Foreign vehicle.....Not foreign	

**1 Casualty**

Casualty number.....1	Car passenger.....Not a passenger
Casualty class.....Driver or Rider	PSV passenger.....Not a passenger
Gender.....Female	Seat belt usage.....
Age.....34	School pupil.....Other
Severity.....Slight	School .....
Vehicle no.....1	Pedestrian location..
Ped Direction.....	Pedestrian movement..
	Roadworker injured...

Accident Date BETWEEN '01-Jul-2007' AND '30-Jun-2012'

Accident Reference: T070212      Slight

Accident 90 of 119

Date & time.....Saturday 01/09/2007 08:20	Speed limit.....60 Mph
Grid reference.....605831/295289	Road type.....Single c'way
District.....Breckland	Junction detail.....Not at or within 20m of junction
Primary road.....U33092	Junction control.....
Secondary road.....	Special conditions...None
Weather.....Fine	Carriageway hazards..None
Lighting.....Daylight	Number of vehicles...2
Crossing(human)....No Human control within 50m	Number of casualties..2
Crossing(physical)..No crossing facility within 50m	Surface.....Dry

**Did a police officer attend?**  
Yes

**Accident Description**

Veh 1 (Car), Going ahead right Hand Bend from Northeast to Southwest; Veh 2 (Car), Going ahead left Hand Bend from Southwest to Northeast. Collision Diagram Info: Head on Collision

**2 Vehicles**

Vehicle number.....1	First impact.....Front
Other vehicle.....2	Hit object in c'way..None
Vehicle class.....Car	Hit object off c'way.Tree
Junction location...Not at junction	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Male
Direction.....North east South west	Driver age.....20
Manoeuvres.....Going ahead right hand bend	
Skidding.....Yes & Overturned	Hit and Run.....No
Left c'way.....Left c'way nearside & rebounded	Breath test.....Negative
Towing.....No	Journey purpose.....
Foreign vehicle.....Not foreign	

Vehicle number.....2	First impact.....Front
Other vehicle.....1	Hit object in c'way..None
Vehicle class.....Car	Hit object off c'way.None
Junction location...Not at junction	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Male
Direction.....South west North east	Driver age.....32
Manoeuvres.....Going ahead left hand bend	
Skidding.....No	Hit and Run.....No
Left c'way.....Did not leave c'way	Breath test.....Negative
Towing.....No	Journey purpose.....
Foreign vehicle.....Not foreign	

**2 Casualties**

Casualty number.....1	Car passenger.....Not a passenger
Casualty class.....Driver or Rider	PSV passenger.....Not a passenger
Gender.....Male	Seat belt usage.....
Age.....32	School pupil.....Other
	School .....
Severity.....Slight	Pedestrian location..
Vehicle no.....2	Pedestrian movement..
Ped Direction.....	Roadworker injured...

Casualty number.....2	Car passenger.....Front seat passenger
Casualty class.....Passenger	PSV passenger.....Not a passenger
Gender.....Female	Seat belt usage.....
Age.....30	School pupil.....Other
	School .....
Severity.....Slight	Pedestrian location..
Vehicle no.....2	Pedestrian movement..
Ped Direction.....	Roadworker injured...

Accident Date BETWEEN '01-Jul-2007' AND '30-Jun-2012'

Accident Reference: 0054452      Slight      Norwich Road First Road: B1077, Second Road: 33096      Accident 91 of 119

Date & time.....Tuesday 24/11/2009 07:44	Speed limit.....40 Mph
Grid reference.....605881/296309	Road type.....Single c'way
District.....Breckland	Junction detail.....T or Staggered junction
Primary road.....B1077	Junction control.....Give way sign or uncontrolled
Secondary road.....U33096	Special conditions...None
Weather.....Rain	Carriageway hazards..None
Lighting.....Daylight	Number of vehicles...2
Crossing(human).....No Human control within 50m	Number of casualties.1
Crossing(physical)..No crossing facility within 50m	Surface.....Wet

**Did a police officer attend?**  
Yes

**Accident Description**

Veh 1 (Car), turning right from South to Northeast; Veh 2 (Pedal Cycle), Going ahead Other from Northeast to Southwest. Collision Diagram Info: right Turn Joining Main Road - Head on

**2 Vehicles**

Vehicle number.....1	First impact.....Front
Other vehicle.....2	Hit object in c'way..None
Vehicle class.....Car	Hit object off c'way.None
Junction location...Entering main road	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Female
Direction.....South North east	Driver age.....34
Manoeuvres.....Turning right	
Skidding.....No	Hit and Run.....No
Left c'way.....Did not leave c'way	Breath test.....Negative
Towing.....No	Journey purpose.....Commuting to/from work
Foreign vehicle.....Not foreign	

Vehicle number.....2	First impact.....Nearside
Other vehicle.....1	Hit object in c'way..None
Vehicle class.....Pedal Cycle	Hit object off c'way.None
Junction location...Mid junction	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Female
Direction.....North east South west	Driver age.....37
Manoeuvres.....Going ahead other	
Skidding.....No	Hit and Run.....No
Left c'way.....Did not leave c'way	Breath test.....Not applicable
Towing.....No	Journey purpose.....Commuting to/from work
Foreign vehicle.....Not foreign	

**1 Casualty**

Casualty number.....1	Car passenger.....Not a passenger
Casualty class.....Driver or Rider	PSV passenger.....Not a passenger
Gender.....Female	Seat belt usage.....
Age.....37	School pupil.....Other
	School .....
Severity.....Slight	Pedestrian location..
Vehicle no.....2	Pedestrian movement..
Ped Direction.....	Roadworker injured...

Accident Date BETWEEN '01-Jul-2007' AND '30-Jun-2012'

Accident Reference: 0055884      Slight      Norwich Road First Road: B1077, Second Road: 33096      Accident 92 of 119

Date & time.....Sunday 14/03/2010 11:29	Speed limit.....40 Mph
Grid reference.....605881/296309	Road type.....Single c'way
District.....Breckland	Junction detail.....T or Staggered junction
Primary road.....B1077	Junction control.....Give way sign or uncontrolled
Secondary road.....U33096	Special conditions...None
Weather.....Fine	Carriageway hazards..None
Lighting.....Daylight	Number of vehicles...2
Crossing(human).....No Human control within 50m	Number of casualties.4
Crossing(physical)..No crossing facility within 50m	Surface.....Dry

**Did a police officer attend?**  
Yes

**Accident Description**

Veh 1 (Car), Overtaking Moving Veh on its Offside from Southwest to Northeast; Veh 2 (Car), turning right from Southwest to Southeast.

**2 Vehicles**

Vehicle number.....1	First impact.....Front
Other vehicle.....2	Hit object in c'way..None
Vehicle class.....Car	Hit object off c'way.Other permanent object
Junction location...Mid junction	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Female
Direction.....South west North east	Driver age.....27
Manoeuvres.....O/T moving vehicle on its O/S	
Skidding.....Yes	
Left c'way.....Left c'way Offside	Hit and Run.....No
Towing.....No	Breath test.....Negative
Foreign vehicle.....Not foreign	Journey purpose.....Other

Vehicle number.....2	First impact.....Offside
Other vehicle.....1	Hit object in c'way..None
Vehicle class.....Car	Hit object off c'way.None
Junction location...Leaving main road	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Female
Direction.....South west South east	Driver age.....34
Manoeuvres.....Turning right	
Skidding.....No	
Left c'way.....Left c'way Offside	Hit and Run.....No
Towing.....No	Breath test.....Negative
Foreign vehicle.....Not foreign	Journey purpose.....Other

**4 Casualties**

Casualty number.....1	Car passenger.....Not a passenger
Casualty class.....Driver or Rider	PSV passenger.....Not a passenger
Gender.....Female	Seat belt usage.....
Age.....27	School pupil.....Other
	School .....
Severity.....Slight	Pedestrian location..
Vehicle no.....1	Pedestrian movement..
Ped Direction.....	Roadworker injured...
Casualty number.....2	Car passenger.....Not a passenger
Casualty class.....Driver or Rider	PSV passenger.....Not a passenger
Gender.....Female	Seat belt usage.....
Age.....34	School pupil.....Other
	School .....
Severity.....Slight	Pedestrian location..
Vehicle no.....2	Pedestrian movement..
Ped Direction.....	Roadworker injured...
Casualty number.....3	Car passenger.....Rear seat passenger
Casualty class.....Passenger	PSV passenger.....Not a passenger
Gender.....Female	Seat belt usage.....
Age.....8	School pupil.....Other
	School .....
Severity.....Slight	Pedestrian location..
Vehicle no.....2	Pedestrian movement..
Ped Direction.....	Roadworker injured...
Casualty number.....4	Car passenger.....Rear seat passenger
Casualty class.....Passenger	PSV passenger.....Not a passenger
Gender.....Female	Seat belt usage.....
Age.....4	School pupil.....Other
	School .....
Severity.....Slight	Pedestrian location..
Vehicle no.....2	Pedestrian movement..
Ped Direction.....	Roadworker injured...

Accident Date BETWEEN '01-Jul-2007' AND '30-Jun-2012'

Accident Reference: 0062104      Slight      Norwich Road First Road: B1077      Accident 93 of 119

Date & time.....Saturday 30/07/2011 13:40	Speed limit.....60 Mph
Grid reference.....606038/296570	Road type.....Dual c'way
District.....Breckland	Junction detail.....Not at or within 20m of junction
Primary road.....B1077	Junction control.....
Secondary road.....	Special conditions...None
Weather.....Fine	Carriageway hazards..None
Lighting.....Daylight	Number of vehicles...2
Crossing(human).....No Human control within 50m	Number of casualties.1
Crossing(physical)..No crossing facility within 50m	Surface.....Dry

**Did a police officer attend?**  
Yes

**Accident Description**

Veh 1 (Car), Going ahead left Hand Bend from Southwest to North; Veh 2 (Car), Going ahead Other from North to Southwest.

**2 Vehicles**

Vehicle number.....1	First impact.....Back
Other vehicle.....0	Hit object in c'way..Bollard/refuge
Vehicle class.....Car	Hit object off c'way.Other permanent object
Junction location...Not at junction	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Male
Direction.....South west North	Driver age.....23
Manoeuvres.....Going ahead left hand bend	
Skidding.....Yes	Hit and Run.....No
Left c'way.....Left c'way nearside & rebounded	Breath test.....Negative
Towing.....No	Journey purpose.....Other
Foreign vehicle.....Not foreign	

Vehicle number.....2	First impact.....Did not impact
Other vehicle.....0	Hit object in c'way..None
Vehicle class.....Car	Hit object off c'way.None
Junction location...Not at junction	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Male
Direction.....North South west	Driver age.....43
Manoeuvres.....Going ahead other	
Skidding.....No	Hit and Run.....No
Left c'way.....Did not leave c'way	Breath test.....Negative
Towing.....No	Journey purpose.....Other
Foreign vehicle.....Not foreign	

**1 Casualty**

Casualty number.....1	Car passenger.....Not a passenger
Casualty class.....Driver or Rider	PSV passenger.....Not a passenger
Gender.....Male	Seat belt usage.....
Age.....23	School pupil.....Other
	School .....
Severity.....Slight	Pedestrian location..
Vehicle no.....1	Pedestrian movement..
Ped Direction.....	Roadworker injured...

Accident Date BETWEEN '01-Jul-2007' AND '30-Jun-2012'

Accident Reference: 0060250      Slight      Norwich Road First Road: B1077, Second Road: A11      Accident 94 of 119

Date & time.....Sunday 27/02/2011 11:30	Speed limit.....60 Mph
Grid reference.....606137/296769	Road type.....Single c'way
District.....Breckland	Junction detail.....T or Staggered junction
Primary road.....B1077	Junction control.....Give way sign or uncontrolled
Secondary road.....A11	Special conditions...None
Weather.....Fine	Carriageway hazards..None
Lighting.....Daylight	Number of vehicles...1
Crossing(human).....No Human control within 50m	Number of casualties.1
Crossing(physical)..No crossing facility within 50m	Surface.....Dry

**Did a police officer attend?**  
Yes

**Accident Description**

Veh 1 (Car), turning left from East to Southwest.

**1 Vehicle**

Vehicle number.....1	First impact.....Front
Other vehicle.....0	Hit object in c'way..None
Vehicle class.....Car	Hit object off c'way.None
Junction location...Entering from slip road	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Male
Direction.....East South west	Driver age.....40
Manoeuvres.....Turning left	
Skidding.....No	Hit and Run.....No
Left c'way.....Did not leave c'way	Breath test.....Not requested
Towing.....Single Trailer	Journey purpose.....Other
Foreign vehicle.....Not foreign	

**1 Casualty**

Casualty number.....1	Car passenger.....Not a passenger
Casualty class.....Pedestrian	PSV passenger.....Not a passenger
Gender.....Female	Seat belt usage.....
Age.....30	School pupil.....Other
	School .....
Severity.....Slight	Pedestrian location..In carriageway, crossing elsewhere
Vehicle no.....1	Pedestrian movement..Crossing from driver's offside
Ped Direction.....South bound	Roadworker injured...Not applicable



Accident Date BETWEEN '01-Jul-2007' AND '30-Jun-2012'

Accident Reference: 0052552      Slight      First Road: A11, Second Road: A11      Accident 96 of 119

Date & time.....Monday 06/07/2009 15:10	Speed limit.....70 Mph
Grid reference.....606170/296650	Road type.....Dual c'way
District.....Breckland	Junction detail.....Slip Road
Primary road.....A11	Junction control.....Give way sign or uncontrolled
Secondary road.....A11	Special conditions...None
Weather.....Fine	Carriageway hazards..None
Lighting.....Daylight	Number of vehicles...1
Crossing(human).....No Human control within 50m	Number of casualties..1
Crossing(physical)..No crossing facility within 50m	Surface.....Dry

**Did a police officer attend?**  
Yes

**Accident Description**

Veh 1 (Car), Going ahead Other from Northeast to Southwest. Collision Diagram Info: Losing Control

**1 Vehicle**

Vehicle number.....1	First impact.....Offside
Other vehicle.....0	Hit object in c'way..Bollard/refuge
Vehicle class.....Car	Hit object off c'way.None
Junction location...Mid junction	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Female
Direction.....North east South west	Driver age.....29
Manoeuvres.....Going ahead other	
Skidding.....No	Hit and Run.....No
Left c'way.....Left c'way near-side	Breath test.....Not requested
Towing.....No	Journey purpose.....Taking pupil to/from school
Foreign vehicle.....Not foreign	

**1 Casualty**

Casualty number.....1	Car passenger.....Not a passenger
Casualty class.....Driver or Rider	PSV passenger.....Not a passenger
Gender.....Female	Seat belt usage.....
Age.....29	School pupil.....Other
	School .....
Severity.....Slight	Pedestrian location..
Vehicle no.....1	Pedestrian movement..
Ped Direction.....	Roadworker injured...

Accident Date BETWEEN '01-Jul-2007' AND '30-Jun-2012'

Accident Reference: T080100      Serious      Accident 97 of 119

Date & time.....Sunday 11/05/2008 16:27	Speed limit.....70 Mph
Grid reference.....606203/296774	Road type.....Dual c'way
District.....Breckland	Junction detail.....Not at or within 20m of junction
Primary road.....A11	Junction control.....
Secondary road.....	Special conditions...None
Weather.....Fine	Carriageway hazards..None
Lighting.....Daylight	Number of vehicles...1
Crossing(human)....No Human control within 50m	Number of casualties.1
Crossing(physical)..No crossing facility within 50m	Surface.....Dry

**Did a police officer attend?**  
Yes

**Accident Description**

Veh 1 (Goods Vehicle <= 3.5T), Going ahead Other from Northeast to Southwest. Collision Diagram Info: Losing Control

**1 Vehicle**

Vehicle number.....1	First impact.....Front
Other vehicle.....0	Hit object in c'way..None
Vehicle class.....Van/Goods < 3.5t	Hit object off c'way.Road sign or signal
Junction location...Not at junction	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Male
Direction.....North east South west	Driver age.....44
Manoeuvres.....Going ahead other	Hit and Run.....No
Skidding.....Yes & Overturned	Breath test.....Negative
Left c'way.....Left c'way near-side	Journey purpose.....
Towing.....No	
Foreign vehicle.....Not foreign	

**1 Casualty**

Casualty number.....1	Car passenger.....Not a passenger
Casualty class.....Driver or Rider	PSV passenger.....Not a passenger
Gender.....Male	Seat belt usage.....
Age.....44	School pupil.....Other
Severity.....Serious	School .....
Vehicle no.....1	Pedestrian location..
Ped Direction.....	Pedestrian movement..
	Roadworker injured...

Accident Date BETWEEN '01-Jul-2007' AND '30-Jun-2012'

Accident Reference: 0053674      Slight      Norwich Road First Road: C572, Second Road: 33097      Accident 98 of 119

Date & time.....Wednesday 30/09/2009 21:49	Speed limit.....60 Mph
Grid reference.....606221/296929	Road type.....Single c'way
District.....Breckland	Junction detail.....T or Staggered junction
Primary road.....C572	Junction control.....Give way sign or uncontrolled
Secondary road.....U33097	Special conditions...None
Weather.....Fine	Carriageway hazards..None
Lighting.....Dark/no lights	Number of vehicles...2
Crossing(human)....No Human control within 50m	Number of casualties.1
Crossing(physical)..No crossing facility within 50m	Surface.....Dry

**Did a police officer attend?**  
Yes

**Accident Description**

Veh 1 (Car), turning right from Northeast to Southwest; Veh 2 (Car), Going ahead Other from Southwest to Northeast. Collision Diagram Info: right Turn Joining Main Road - Head on

**2 Vehicles**

Vehicle number.....1	First impact.....Front
Other vehicle.....2	Hit object in c'way..None
Vehicle class.....Car	Hit object off c'way.None
Junction location...Entering main road	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Male
Direction.....North east South west	Driver age.....22
Manoeuvres.....Turning right	
Skidding.....No	Hit and Run.....No
Left c'way.....Did not leave c'way	Breath test.....Negative
Towing.....No	Journey purpose.....Other
Foreign vehicle....Not foreign	

Vehicle number.....2	First impact.....Nearside
Other vehicle.....1	Hit object in c'way..None
Vehicle class.....Car	Hit object off c'way.None
Junction location...Mid junction	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Female
Direction.....South west North east	Driver age.....41
Manoeuvres.....Going ahead other	
Skidding.....No	Hit and Run.....No
Left c'way.....Did not leave c'way	Breath test.....Negative
Towing.....No	Journey purpose.....Other
Foreign vehicle....Not foreign	

**1 Casualty**

Casualty number.....1	Car passenger.....Front seat passenger
Casualty class.....Passenger	PSV passenger.....Not a passenger
Gender.....Female	Seat belt usage.....
Age.....16	School pupil.....Other
	School .....
Severity.....Slight	Pedestrian location..
Vehicle no.....1	Pedestrian movement..
Ped Direction.....	Roadworker injured...

Accident Date BETWEEN '01-Jul-2007' AND '30-Jun-2012'

Accident Reference: 0053086      Slight      First Road: A11      Accident 99 of 119

Date & time.....Saturday 15/08/2009 11:08	Speed limit.....70 Mph
Grid reference.....606310/296740	Road type.....Dual c'way
District.....Breckland	Junction detail.....Not at or within 20m of junction
Primary road.....A11	Junction control.....
Secondary road.....	Special conditions...None
Weather.....Fine	Carriageway hazards..None
Lighting.....Daylight	Number of vehicles...2
Crossing(human)....No Human control within 50m	Number of casualties.2
Crossing(physical)..No crossing facility within 50m	Surface.....Dry

**Did a police officer attend?**  
Yes

**Accident Description**

Veh 1 (Car), Going ahead Other from Southwest to Northeast; Veh 2 (Car), Changing Lane to left from Southwest to Northeast. Collision Diagram Info: Changing Lanes to left

**2 Vehicles**

Vehicle number.....1	First impact.....Front
Other vehicle.....2	Hit object in c'way..None
Vehicle class.....Car	Hit object off c'way..Entered ditch
Junction location...Not at junction	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Male
Direction.....South west North east	Driver age.....42
Manoeuvres.....Going ahead other	
Skidding.....Yes & Overturned	
Left c'way.....Left c'way near-side	Hit and Run.....No
Towing.....No	Breath test.....Negative
Foreign vehicle....Not foreign	Journey purpose.....Other

Vehicle number.....2	First impact.....Front
Other vehicle.....1	Hit object in c'way..None
Vehicle class.....Car	Hit object off c'way..None
Junction location...Not at junction	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Male
Direction.....South west North east	Driver age.....52
Manoeuvres.....Changing lane to left	
Skidding.....No	
Left c'way.....Did not leave c'way	Hit and Run.....Yes
Towing.....No	Breath test.....Negative
Foreign vehicle....Not foreign	Journey purpose.....Other

**2 Casualties**

Casualty number.....1	Car passenger.....Not a passenger
Casualty class.....Driver or Rider	PSV passenger.....Not a passenger
Gender.....Male	Seat belt usage.....
Age.....42	School pupil.....Other
	School .....
Severity.....Slight	Pedestrian location..
Vehicle no.....1	Pedestrian movement..
Ped Direction.....	Roadworker injured...
Casualty number.....2	Car passenger.....Front seat passenger
Casualty class.....Passenger	PSV passenger.....Not a passenger
Gender.....Female	Seat belt usage.....
Age.....27	School pupil.....Other
	School .....
Severity.....Slight	Pedestrian location..
Vehicle no.....1	Pedestrian movement..
Ped Direction.....	Roadworker injured...

Accident Date BETWEEN '01-Jul-2007' AND '30-Jun-2012'

Accident Reference: 0058741      Slight      First Road: A11, Second Road: A11      Accident 100 of 119

Date & time.....Tuesday 26/10/2010 18:50	Speed limit.....70 Mph
Grid reference.....606360/296770	Road type.....Dual c'way
District.....Breckland	Junction detail.....Slip Road
Primary road.....A11	Junction control.....Give way sign or uncontrolled
Secondary road.....A11	Special conditions...None
Weather.....Rain	Carriageway hazards..None
Lighting.....Dark/no lights	Number of vehicles...2
Crossing(human).....No Human control within 50m	Number of casualties.1
Crossing(physical)..No crossing facility within 50m	Surface.....Wet

**Did a police officer attend?**  
Yes

**Accident Description**

Veh 1 (Goods Vehicle <= 3.5T), Going ahead Other from Southwest to Northeast; Veh 2 (Car), Slowing or Stopping from Southwest to Northeast.

**2 Vehicles**

Vehicle number.....1	First impact.....Front
Other vehicle.....2	Hit object in c'way..None
Vehicle class.....Van/Goods < 3.5t	Hit object off c'way.None
Junction location...Approaching or parked on approach to	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Male
Direction.....South west North east	Driver age.....44
Manoeuvres.....Going ahead other	
Skidding.....Yes	Hit and Run.....No
Left c'way.....Left c'way near-side	Breath test.....Negative
Towing.....No	Journey purpose.....Journey as part of work
Foreign vehicle.....Not foreign	

Vehicle number.....2	First impact.....Back
Other vehicle.....1	Hit object in c'way..None
Vehicle class.....Car	Hit object off c'way.None
Junction location...Approaching or parked on approach to	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Male
Direction.....South west North east	Driver age.....38
Manoeuvres.....Stopping	
Skidding.....No	Hit and Run.....No
Left c'way.....Did not leave c'way	Breath test.....Negative
Towing.....No	Journey purpose.....Other
Foreign vehicle.....Not foreign	

**1 Casualty**

Casualty number.....1	Car passenger.....Front seat passenger
Casualty class.....Passenger	PSV passenger.....Not a passenger
Gender.....Female	Seat belt usage.....
Age.....23	School pupil.....Other
	School .....
Severity.....Slight	Pedestrian location..
Vehicle no.....2	Pedestrian movement..
Ped Direction.....	Roadworker injured...

Accident Date BETWEEN '01-Jul-2007' AND '30-Jun-2012'

Accident Reference: 0065900      Slight      First Road: C572      Accident 101 of 119

Date & time.....Friday 01/06/2012 13:30	Speed limit.....60 Mph
Grid reference.....606530/296070	Road type.....Single c'way
District.....Breckland	Junction detail.....Not at or within 20m of junction
Primary road.....C572	Junction control.....
Secondary road.....	Special conditions...None
Weather.....Fine	Carriageway hazards..None
Lighting.....Daylight	Number of vehicles...1
Crossing(human).....No Human control within 50m	Number of casualties..1
Crossing(physical)..No crossing facility within 50m	Surface.....Dry

**Did a police officer attend?**  
Yes

**Accident Description**

Veh 1 (M/Cycle upto 125Cc), Going ahead Other from Northeast to Southwest.

**1 Vehicle**

Vehicle number.....1	First impact.....Front
Other vehicle.....0	Hit object in c'way..None
Vehicle class.....M/cycle 50 - 125cc	Hit object off c'way..None
Junction location...Not at junction	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Male
Direction.....North east South west	Driver age.....31
Manoeuvres.....Going ahead other	
Skidding.....No	Hit and Run.....No
Left c'way.....Did not leave c'way	Breath test.....Not contacted
Towing.....No	Journey purpose.....Other
Foreign vehicle.....Not foreign	

**1 Casualty**

Casualty number.....1	Car passenger.....Not a passenger
Casualty class.....Driver or Rider	PSV passenger.....Not a passenger
Gender.....Male	Seat belt usage.....
Age.....31	School pupil.....Other
	School .....
Severity.....Slight	Pedestrian location..
Vehicle no.....1	Pedestrian movement..
Ped Direction.....	Roadworker injured...

Accident Date BETWEEN '01-Jul-2007' AND '30-Jun-2012'

Accident Reference:0050336      Slight      Borough Lane First Road: 33089, Second Road: 33091      Accident 102 of 119

Date & time.....Saturday 24/01/2009 21:55	Speed limit.....60 Mph
Grid reference.....606580/294290	Road type.....Single c'way
District.....Breckland	Junction detail.....Other Junction
Primary road.....U33089	Junction control.....Give way sign or uncontrolled
Secondary road.....U33091	Special conditions...None
Weather.....Fine	Carriageway hazards..None
Lighting.....Dark/no lights	Number of vehicles...1
Crossing(human)....No Human control within 50m	Number of casualties.1
Crossing(physical)..No crossing facility within 50m	Surface.....Ice

**Did a police officer attend?**  
Yes

**Accident Description**

Veh 1 (Car), Going ahead left Hand Bend from Southwest to North. Collision Diagram Info: Losing Control - left Hand Bend

**1 Vehicle**

Vehicle number.....1	First impact.....Offside
Other vehicle.....0	Hit object in c'way..None
Vehicle class.....Car	Hit object off c'way.Entered ditch
Junction location...Mid junction	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Male
Direction.....South west North	Driver age.....32
Manoeuvres.....Going ahead left hand bend	
Skidding.....Yes & Overturned	Hit and Run.....No
Left c'way.....Left c'way Offside	Breath test.....Negative
Towing.....No	Journey purpose.....Other
Foreign vehicle.....Not foreign	

**1 Casualty**

Casualty number.....1	Car passenger.....Front seat passenger
Casualty class.....Passenger	PSV passenger.....Not a passenger
Gender.....Female	Seat belt usage.....
Age.....48	School pupil.....Other
	School .....
Severity.....Slight	Pedestrian location..
Vehicle no.....1	Pedestrian movement..
Ped Direction.....	Roadworker injured...

Accident Date BETWEEN '01-Jul-2007' AND '30-Jun-2012'

Accident Reference: 0060190      Slight      First Road: A11      Accident 103 of 119

Date & time.....Thursday 24/02/2011 02:18	Speed limit.....70 Mph
Grid reference.....606610/296880	Road type.....Dual c'way
District.....Breckland	Junction detail.....Not at or within 20m of junction
Primary road.....A11	Junction control.....
Secondary road.....	Special conditions...None
Weather.....Fine	Carriageway hazards..None
Lighting.....Dark/no lights	Number of vehicles...1
Crossing(human)....No Human control within 50m	Number of casualties.1
Crossing(physical)..No crossing facility within 50m	Surface.....Wet

**Did a police officer attend?**  
Yes

**Accident Description**

Veh 1 (Car), Going ahead Other from Southwest to Northeast.

**1 Vehicle**

Vehicle number.....1	First impact.....Front
Other vehicle.....0	Hit object in c'way..None
Vehicle class.....Car	Hit object off c'way.Nearside/offside crash barrier
Junction location...Not at junction	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Male
Direction.....South west North east	Driver age.....22
Manoeuvres.....Going ahead other	
Skidding.....No	Hit and Run.....No
Left c'way.....Left c'way near-side	Breath test.....Negative
Towing.....No	Journey purpose.....Other
Foreign vehicle.....Not foreign	

**1 Casualty**

Casualty number.....1	Car passenger.....Not a passenger
Casualty class.....Driver or Rider	PSV passenger.....Not a passenger
Gender.....Male	Seat belt usage.....
Age.....22	School pupil.....Other
	School .....
Severity.....Slight	Pedestrian location..
Vehicle no.....1	Pedestrian movement..
Ped Direction.....	Roadworker injured...

Accident Date BETWEEN '01-Jul-2007' AND '30-Jun-2012'

Accident Reference: 0061754      Slight      First Road: A11      Accident 104 of 119

Date & time.....Tuesday 05/07/2011 10:30	Speed limit.....70 Mph
Grid reference.....606840/296970	Road type.....Dual c'way
District.....Breckland	Junction detail.....Not at or within 20m of junction
Primary road.....A11	Junction control.....
Secondary road.....	Special conditions...None
Weather.....Fine	Carriageway hazards..None
Lighting.....Daylight	Number of vehicles...3
Crossing(human).....No Human control within 50m	Number of casualties..1
Crossing(physical)..No crossing facility within 50m	Surface.....Dry

**Did a police officer attend?**  
Yes

**Accident Description**

Veh 1 (Car), Moving off from Southwest to Northeast; Veh 2 (Car), Going ahead Other from Southwest to Northeast; Veh 3 (Car), Going ahead Other from Southwest to Northeast.

**3 Vehicles**

Vehicle number.....1	First impact.....Did not impact
Other vehicle.....0	Hit object in c'way..None
Vehicle class.....Car	Hit object off c'way..None
Junction location...Not at junction	Parts damaged..... / /
Restricted location..Leaving lay-by	Driver gender.....Not known
Direction.....South west North east	Driver age.....-1
Manoeuvres.....Starting	
Skidding.....No	Hit and Run.....Non-stop vehicle, not hit
Left c'way.....Did not leave c'way	Breath test.....Not contacted
Towing.....No	Journey purpose.....Other
Foreign vehicle.....Not foreign	

Vehicle number.....2	First impact.....Back
Other vehicle.....3	Hit object in c'way..None
Vehicle class.....Car	Hit object off c'way..None
Junction location...Not at junction	Parts damaged..... / /
Restricted location..On main carriageway	Driver gender.....Female
Direction.....South west North east	Driver age.....30
Manoeuvres.....Going ahead other	
Skidding.....Yes	Hit and Run.....No
Left c'way.....Did not leave c'way	Breath test.....Negative
Towing.....No	Journey purpose.....Other
Foreign vehicle.....Not foreign	

Vehicle number.....3	First impact.....Front
Other vehicle.....2	Hit object in c'way..None
Vehicle class.....Car	Hit object off c'way..None
Junction location...Not at junction	Parts damaged..... / /
Restricted location..On main carriageway	Driver gender.....Male
Direction.....South west North east	Driver age.....63
Manoeuvres.....Going ahead other	
Skidding.....Yes	Hit and Run.....No
Left c'way.....Did not leave c'way	Breath test.....Negative
Towing.....No	Journey purpose.....Other
Foreign vehicle.....Not foreign	

**1 Casualty**

Casualty number.....1	Car passenger.....Front seat passenger
Casualty class.....Passenger	PSV passenger.....Not a passenger
Gender.....Female	Seat belt usage.....
Age.....61	School pupil.....Other
	School .....
Severity.....Slight	Pedestrian location..
Vehicle no.....3	Pedestrian movement..
Ped Direction.....	Roadworker injured...

Accident Date BETWEEN '01-Jul-2007' AND '30-Jun-2012'

Accident Reference: 0057872      Slight      First Road: A11      Accident 105 of 119

Date & time.....Sunday 22/08/2010 15:25	Speed limit.....70 Mph
Grid reference.....607080/297080	Road type.....Dual c'way
District.....Breckland	Junction detail.....Not at or within 20m of junction
Primary road.....A11	Junction control.....
Secondary road.....	Special conditions...None
Weather.....Fine	Carriageway hazards..None
Lighting.....Daylight	Number of vehicles...2
Crossing(human)....No Human control within 50m	Number of casualties.2
Crossing(physical)..No crossing facility within 50m	Surface.....Dry

**Did a police officer attend?**  
Yes

**Accident Description**

Veh 1 (Car), Going ahead Other from Northeast to Southwest; Veh 2 (Car), Going ahead Other from Northeast to Southwest.

**2 Vehicles**

Vehicle number.....1	First impact.....Back
Other vehicle.....2	Hit object in c'way..None
Vehicle class.....Car	Hit object off c'way.Nearside/offside crash barrier
Junction location...Not at junction	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Male
Direction.....North east South west	Driver age.....45
Manoeuvres.....Going ahead other	
Skidding.....Yes	Hit and Run.....No
Left c'way.....Left c'way nearside & rebounded	Breath test.....Negative
Towing.....No	Journey purpose.....Other
Foreign vehicle....Not foreign	

Vehicle number.....2	First impact.....Front
Other vehicle.....1	Hit object in c'way..None
Vehicle class.....Car	Hit object off c'way.Nearside/offside crash barrier
Junction location...Not at junction	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Female
Direction.....North east South west	Driver age.....21
Manoeuvres.....Going ahead other	
Skidding.....Yes & Overturned	Hit and Run.....No
Left c'way.....Left c'way nearside & rebounded	Breath test.....Negative
Towing.....No	Journey purpose.....Other
Foreign vehicle....Not foreign	

**2 Casualties**

Casualty number.....1	Car passenger.....Not a passenger
Casualty class.....Driver or Rider	PSV passenger.....Not a passenger
Gender.....Female	Seat belt usage.....
Age.....21	School pupil.....Other
	School .....
Severity.....Slight	Pedestrian location..
Vehicle no.....2	Pedestrian movement..
Ped Direction.....	Roadworker injured...
Casualty number.....2	Car passenger.....Front seat passenger
Casualty class.....Passenger	PSV passenger.....Not a passenger
Gender.....Female	Seat belt usage.....
Age.....21	School pupil.....Other
	School .....
Severity.....Slight	Pedestrian location..
Vehicle no.....2	Pedestrian movement..
Ped Direction.....	Roadworker injured...

Accident Date BETWEEN '01-Jul-2007' AND '30-Jun-2012'

Accident Reference: 46650                      Slight

Accident 106 of 119

Date & time.....Monday 05/05/2008 19:46	Speed limit.....70 Mph
Grid reference.....607180/297127	Road type.....Dual c'way
District.....Breckland	Junction detail.....Not at or within 20m of junction
Primary road.....A11	Junction control.....
Secondary road.....	Special conditions...None
Weather.....Fine	Carriageway hazards..None
Lighting.....Daylight	Number of vehicles...1
Crossing(human)....No Human control within 50m	Number of casualties..2
Crossing(physical)..No crossing facility within 50m	Surface.....Dry

**Did a police officer attend?**  
Yes

**Accident Description**

Veh 1 (Car), Going ahead Other from Southwest to Northeast. Collision Diagram Info: Losing Control

**1 Vehicle**

Vehicle number.....1	First impact.....Front
Other vehicle.....0	Hit object in c'way..None
Vehicle class.....Car	Hit object off c'way.Road sign or signal
Junction location...Not at junction	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Female
Direction.....South west North east	Driver age.....28
Manoeuvres.....Going ahead other	
Skidding.....No	Hit and Run.....No
Left c'way.....Left c'way near-side	Breath test.....Negative
Towing.....No	Journey purpose.....
Foreign vehicle....Not foreign	

**2 Casualties**

Casualty number.....1	Car passenger.....Not a passenger
Casualty class.....Driver or Rider	PSV passenger.....Not a passenger
Gender.....Female	Seat belt usage.....
Age.....28	School pupil.....Other
	School .....
Severity.....Slight	Pedestrian location..
Vehicle no.....1	Pedestrian movement..
Ped Direction.....	Roadworker injured...
<hr/>	
Casualty number.....2	Car passenger.....Front seat passenger
Casualty class.....Passenger	PSV passenger.....Not a passenger
Gender.....Male	Seat belt usage.....
Age.....27	School pupil.....Other
	School .....
Severity.....Slight	Pedestrian location..
Vehicle no.....1	Pedestrian movement..
Ped Direction.....	Roadworker injured...

Accident Date BETWEEN '01-Jul-2007' AND '30-Jun-2012'

Accident Reference: 0050317      Slight      First Road: A11      Accident 107 of 119

Date & time.....Monday 19/01/2009 06:39	Speed limit.....70 Mph
Grid reference.....607220/297170	Road type.....Dual c'way
District.....Breckland	Junction detail.....Other Junction
Primary road.....A11	Junction control.....Give way sign or uncontrolled
Secondary road.....	Special conditions...None
Weather.....Rain	Carriageway hazards..None
Lighting.....Dark/unknown	Number of vehicles...3
Crossing(human)....No Human control within 50m	Number of casualties..1
Crossing(physical)..No crossing facility within 50m	Surface.....Wet

**Did a police officer attend?**  
Yes

**Accident Description**

Veh 1 (Car), turning left from Northwest to Northeast; Veh 2 (Car), Going ahead Other from Southwest to Northeast; Veh 3 (Car), Going ahead Other from Southwest to Northeast. Collision Diagram Info: Losing Control

**3 Vehicles**

Vehicle number.....1	First impact.....Did not impact
Other vehicle.....0	Hit object in c'way..None
Vehicle class.....Car	Hit object off c'way..None
Junction location...Entering main road	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Male
Direction.....North west North east	Driver age.....24
Manoeuvres.....Turning left	
Skidding.....No	Hit and Run.....No
Left c'way.....Did not leave c'way	Breath test.....Negative
Towing.....No	Journey purpose.....Other
Foreign vehicle....Not foreign	

Vehicle number.....2	First impact.....Did not impact
Other vehicle.....0	Hit object in c'way..None
Vehicle class.....Car	Hit object off c'way..None
Junction location...Mid junction	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Male
Direction.....South west North east	Driver age.....62
Manoeuvres.....Going ahead other	
Skidding.....No	Hit and Run.....No
Left c'way.....Did not leave c'way	Breath test.....Negative
Towing.....No	Journey purpose.....Other
Foreign vehicle....Not foreign	

Vehicle number.....3	First impact.....Offside
Other vehicle.....0	Hit object in c'way..None
Vehicle class.....Car	Hit object off c'way..None
Junction location...Cleared junction or parked at junctio	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Male
Direction.....South west North east	Driver age.....29
Manoeuvres.....Going ahead other	
Skidding.....Yes	Hit and Run.....No
Left c'way.....Left c'way offside onto central res.	Breath test.....Negative
Towing.....No	Journey purpose.....Other
Foreign vehicle....Not foreign	

**1 Casualty**

Casualty number.....1	Car passenger.....Not a passenger
Casualty class.....Driver or Rider	PSV passenger.....Not a passenger
Gender.....Male	Seat belt usage.....
Age.....29	School pupil.....Other
	School .....
Severity.....Slight	Pedestrian location..
Vehicle no.....3	Pedestrian movement..
Ped Direction.....	Roadworker injured...

Accident Date BETWEEN '01-Jul-2007' AND '30-Jun-2012'

Accident Reference: 0050344      Slight      First Road: A11      Accident 108 of 119

Date & time.....Sunday 25/01/2009 18:24	Speed limit.....70 Mph
Grid reference.....607220/297170	Road type.....Dual c'way
District.....Breckland	Junction detail.....Using private drive or entrance
Primary road.....A11	Junction control.....Give way sign or uncontrolled
Secondary road.....	Special conditions...None
Weather.....Rain	Carriageway hazards..Previous accident
Lighting.....Dark/no lights	Number of vehicles...3
Crossing(human)....No Human control within 50m	Number of casualties..2
Crossing(physical)..No crossing facility within 50m	Surface.....Wet

**Did a police officer attend?**  
Yes

**Accident Description**

Veh 1 (Car), Going ahead Other from Southwest to Northeast; Veh 2 (Car), Going ahead Other from Southwest to Northeast; Veh 3 (Car), turning right from Northwest to Northeast. Collision Diagram Info: Tail End Collision

**3 Vehicles**

Vehicle number.....1	First impact.....Offside
Other vehicle.....0	Hit object in c'way..Previous accident
Vehicle class.....Car	Hit object off c'way..Central crash barrier
Junction location...Cleared junction or parked at junctio	Parts damaged..... / /
Restricted location..On main carriageway	Driver gender.....Male
Direction.....South west North east	Driver age.....66
Manoeuvres.....Going ahead other	
Skidding.....Yes	
Left c'way.....Left c'way offside onto central res.	Hit and Run.....No
Towing.....No	Breath test.....Negative
Foreign vehicle....Not foreign	Journey purpose.....Other

Vehicle number.....2	First impact.....Front
Other vehicle.....3	Hit object in c'way..None
Vehicle class.....Car	Hit object off c'way..None
Junction location...Cleared junction or parked at junctio	Parts damaged..... / /
Restricted location..On main carriageway	Driver gender.....Female
Direction.....South west North east	Driver age.....44
Manoeuvres.....Going ahead other	
Skidding.....Yes	
Left c'way.....Did not leave c'way	Hit and Run.....No
Towing.....No	Breath test.....Negative
Foreign vehicle....Not foreign	Journey purpose.....Other

Vehicle number.....3	First impact.....Back
Other vehicle.....2	Hit object in c'way..None
Vehicle class.....Car	Hit object off c'way..None
Junction location...Entering main road	Parts damaged..... / /
Restricted location..On main carriageway	Driver gender.....Male
Direction.....North west North east	Driver age.....29
Manoeuvres.....Turning right	
Skidding.....No	
Left c'way.....Did not leave c'way	Hit and Run.....No
Towing.....No	Breath test.....Negative
Foreign vehicle....Not foreign	Journey purpose.....Other

**2 Casualties**

Casualty number.....1	Car passenger.....Not a passenger
Casualty class.....Driver or Rider	PSV passenger.....Not a passenger
Gender.....Female	Seat belt usage.....
Age.....44	School pupil.....Other
	School .....
Severity.....Slight	Pedestrian location..
Vehicle no.....2	Pedestrian movement..
Ped Direction.....	Roadworker injured...

Casualty number.....2	Car passenger.....Not a passenger
Casualty class.....Driver or Rider	PSV passenger.....Not a passenger
Gender.....Male	Seat belt usage.....
Age.....29	School pupil.....Other
	School .....
Severity.....Slight	Pedestrian location..
Vehicle no.....3	Pedestrian movement..
Ped Direction.....	Roadworker injured...



Accident Date BETWEEN '01-Jul-2007' AND '30-Jun-2012'

Accident Reference: 0056645      Serious      First Road: A11      Accident 110 of 119

Date & time.....Sunday 23/05/2010 14:13	Speed limit.....70 Mph
Grid reference.....607250/297160	Road type.....Dual c'way
District.....Breckland	Junction detail.....Not at or within 20m of junction
Primary road.....A11	Junction control.....
Secondary road.....	Special conditions...None
Weather.....Fine	Carriageway hazards..None
Lighting.....Daylight	Number of vehicles...3
Crossing(human)....No Human control within 50m	Number of casualties.2
Crossing(physical)..No crossing facility within 50m	Surface.....Dry

**Did a police officer attend?**  
Yes

**Accident Description**

Veh 1 (Car), Going ahead Other from Northeast to Southwest; Veh 2 (Pedal Cycle), Going ahead Other from Northeast to Southwest; Veh 3 (Pedal Cycle), Going ahead Other from Northeast to Southwest.

**3 Vehicles**

Vehicle number.....1	First impact.....Did not impact
Other vehicle.....0	Hit object in c'way..None
Vehicle class.....Car	Hit object off c'way.None
Junction location...Not at junction	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Male
Direction.....North east South west	Driver age.....29
Manoeuvres.....Going ahead other	
Skidding.....No	
Left c'way.....Did not leave c'way	Hit and Run.....No
Towing.....No	Breath test.....Negative
Foreign vehicle....Not foreign	Journey purpose.....Other

Vehicle number.....2	First impact.....Offside
Other vehicle.....0	Hit object in c'way..None
Vehicle class.....Pedal Cycle	Hit object off c'way.None
Junction location...Not at junction	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Male
Direction.....North east South west	Driver age.....46
Manoeuvres.....Going ahead other	
Skidding.....No	
Left c'way.....Did not leave c'way	Hit and Run.....No
Towing.....No	Breath test.....Not applicable
Foreign vehicle....Not foreign	Journey purpose.....Other

Vehicle number.....3	First impact.....Offside
Other vehicle.....0	Hit object in c'way..None
Vehicle class.....Pedal Cycle	Hit object off c'way.None
Junction location...Not at junction	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Male
Direction.....North east South west	Driver age.....43
Manoeuvres.....Going ahead other	
Skidding.....No	
Left c'way.....Did not leave c'way	Hit and Run.....No
Towing.....No	Breath test.....Not applicable
Foreign vehicle....Not foreign	Journey purpose.....Other

**2 Casualties**

Casualty number.....1	Car passenger.....Not a passenger
Casualty class.....Driver or Rider	PSV passenger.....Not a passenger
Gender.....Male	Seat belt usage.....
Age.....46	School pupil.....Other
	School .....
Severity.....Serious	Pedestrian location..
Vehicle no.....2	Pedestrian movement..
Ped Direction.....	Roadworker injured...

Casualty number.....2	Car passenger.....Not a passenger
Casualty class.....Driver or Rider	PSV passenger.....Not a passenger
Gender.....Male	Seat belt usage.....
Age.....43	School pupil.....Other
	School .....
Severity.....Slight	Pedestrian location..
Vehicle no.....3	Pedestrian movement..
Ped Direction.....	Roadworker injured...

Accident Date BETWEEN '01-Jul-2007' AND '30-Jun-2012'

Accident Reference:0063874	Fatal	A11 Besthorpe 150 Mtrs South of Silver Street Flyover	Accident 111 of 119
Date & time.....Sunday 18/12/2011 03:22		Speed limit.....70 Mph	
Grid reference.....607310/297200		Road type.....Dual c'way	
District.....Breckland		Junction detail.....Not at or within 20m of junction	
Primary road.....A11		Junction control.....	
Secondary road.....		Special conditions...None	
Weather.....Fine		Carriageway hazards..Previous accident	
Lighting.....Dark/lights not lit		Number of vehicles...3	
Crossing(human)....No Human control within 50m		Number of casualties.1	
Crossing(physical)..No crossing facility within 50m		Surface.....Wet	

**Did a police officer attend?**  
Yes

**Accident Description**

V1 > South Hits Res. Driver & Pass Get out of Vehh Driver Hit by V2.

**3 Vehicles**

Vehicle number.....1	First impact.....Offside
Other vehicle.....2	Hit object in c'way..None
Vehicle class.....Car	Hit object off c'way..Central crash barrier
Junction location...Not at junction	Parts damaged..... / /
Restricted location..On main carriageway	Driver gender.....Female
Direction.....North east South west	Driver age.....24
Manoeuvres.....Going ahead other	
Skidding.....Yes	
Left c'way.....Left c'way offside onto central res.	Hit and Run.....No
Towing.....No	Breath test.....Not requested
Foreign vehicle.....Not foreign	Journey purpose.....Commuting to/from work

Vehicle number.....2	First impact.....Front
Other vehicle.....1	Hit object in c'way..Previous accident
Vehicle class.....Car	Hit object off c'way..Central crash barrier
Junction location...Not at junction	Parts damaged..... / /
Restricted location..On main carriageway	Driver gender.....Male
Direction.....North east South west	Driver age.....44
Manoeuvres.....Going ahead other	
Skidding.....Yes	
Left c'way.....Left c'way offside onto central res.	Hit and Run.....No
Towing.....No	Breath test.....Negative
Foreign vehicle.....Not foreign	Journey purpose.....Commuting to/from work

Vehicle number.....3	First impact.....Nearside
Other vehicle.....1	Hit object in c'way..Previous accident
Vehicle class.....Minibus	Hit object off c'way..None
Junction location...Not at junction	Parts damaged..... / /
Restricted location..On main carriageway	Driver gender.....Male
Direction.....North east South west	Driver age.....34
Manoeuvres.....Going ahead other	
Skidding.....Yes	
Left c'way.....Did not leave c'way	Hit and Run.....No
Towing.....No	Breath test.....Negative
Foreign vehicle.....Not foreign	Journey purpose.....Journey as part of work

**1 Casualty**

Casualty number.....1	Car passenger.....Not a passenger
Casualty class.....Driver or Rider	PSV passenger.....Not a passenger
Gender.....Female	Seat belt usage.....
Age.....24	School pupil.....Other
	School .....
Severity.....Fatal	Pedestrian location..
Vehicle no.....1	Pedestrian movement..
Ped Direction.....	Roadworker injured...

Accident Date BETWEEN '01-Jul-2007' AND '30-Jun-2012'

Accident Reference: 0055445      Slight      First Road: A11      Accident 112 of 119

Date & time.....Tuesday 02/02/2010 17:30	Speed limit.....70 Mph
Grid reference.....607390/297240	Road type.....Dual c'way
District.....Breckland	Junction detail.....Not at or within 20m of junction
Primary road.....A11	Junction control.....
Secondary road.....	Special conditions...None
Weather.....Rain	Carriageway hazards..None
Lighting.....Dark/no lights	Number of vehicles...2
Crossing(human)....No Human control within 50m	Number of casualties.1
Crossing(physical)..No crossing facility within 50m	Surface.....Wet

**Did a police officer attend?**  
Yes

**Accident Description**

Veh 1 (Car), Going ahead Other from Northeast to Southwest; Veh 2 (Car), Going ahead Other from Northeast to Southwest. Collision Diagram Info: Tail End Collision

**2 Vehicles**

Vehicle number.....1	First impact.....Front
Other vehicle.....2	Hit object in c'way..None
Vehicle class.....Car	Hit object off c'way.None
Junction location...Not at junction	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Male
Direction.....North east South west	Driver age.....67
Manoeuvres.....Going ahead other	
Skidding.....No	Hit and Run.....No
Left c'way.....Did not leave c'way	Breath test.....Negative
Towing.....No	Journey purpose.....Other
Foreign vehicle....Not foreign	

Vehicle number.....2	First impact.....Back
Other vehicle.....1	Hit object in c'way..None
Vehicle class.....Car	Hit object off c'way.None
Junction location...Not at junction	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Male
Direction.....North east South west	Driver age.....34
Manoeuvres.....Going ahead other	
Skidding.....No	Hit and Run.....No
Left c'way.....Did not leave c'way	Breath test.....Negative
Towing.....No	Journey purpose.....Commuting to/from work
Foreign vehicle....Not foreign	

**1 Casualty**

Casualty number.....1	Car passenger.....Not a passenger
Casualty class.....Driver or Rider	PSV passenger.....Not a passenger
Gender.....Male	Seat belt usage.....
Age.....34	School pupil.....Other
	School .....
Severity.....Slight	Pedestrian location..
Vehicle no.....2	Pedestrian movement..
Ped Direction.....	Roadworker injured...

Accident Date BETWEEN '01-Jul-2007' AND '30-Jun-2012'

Accident Reference: 48436                      Fatal                      Accident 113 of 119

Date & time.....Friday 12/09/2008 00:40	Speed limit.....70 Mph
Grid reference.....607491/297308	Road type.....Dual c'way
District.....Breckland	Junction detail.....Not at or within 20m of junction
Primary road.....A11	Junction control.....
Secondary road.....	Special conditions...None
Weather.....Other	Carriageway hazards..Animal in c'way
Lighting.....Dark/no lights	Number of vehicles...1
Crossing(human)....No Human control within 50m	Number of casualties..2
Crossing(physical)..No crossing facility within 50m	Surface.....Wet

**Did a police  
officer  
attend?**

**Accident Description**

Veh 1 (Car), Going ahead Other from Northeast to Southwest. Collision Diagram Info: Dog or Animal in Carriageway

**1 Vehicle**

Vehicle number.....1	First impact.....Front
Other vehicle.....0	Hit object in c'way..Any animal
Vehicle class.....Car	Hit object off c'way.Tree
Junction location...Not at junction	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Male
Direction.....North east South west	Driver age.....23
Manoeuvres.....Going ahead other	
Skidding.....Yes & Overturned	Hit and Run.....No
Left c'way.....Left c'way straight ahead at junction	Breath test.....Negative
Towing.....No	Journey purpose.....
Foreign vehicle.....Not foreign	

**2 Casualties**

Casualty number.....1	Car passenger.....Front seat passenger
Casualty class.....Passenger	PSV passenger.....Not a passenger
Gender.....Male	Seat belt usage.....
Age.....30	School pupil.....Other
	School .....
Severity.....Fatal	Pedestrian location..
Vehicle no.....1	Pedestrian movement..
Ped Direction.....	Roadworker injured...

---

Casualty number.....2	Car passenger.....Not a passenger
Casualty class.....Driver or Rider	PSV passenger.....Not a passenger
Gender.....Male	Seat belt usage.....
Age.....23	School pupil.....Other
	School .....
Severity.....Slight	Pedestrian location..
Vehicle no.....1	Pedestrian movement..
Ped Direction.....	Roadworker injured...

Accident Date BETWEEN '01-Jul-2007' AND '30-Jun-2012'

Accident Reference: 0063541      Slight      Norwich Road First Road: C572, Second Road: C778      Accident 114 of 119

Date & time.....Thursday 17/11/2011 16:48	Speed limit.....30 Mph
Grid reference.....607579/297592	Road type.....Single c'way
District.....South Norfolk	Junction detail.....T or Staggered junction
Primary road.....C572	Junction control.....Give way sign or uncontrolled
Secondary road.....C778	Special conditions...None
Weather.....Fine	Carriageway hazards..None
Lighting.....Dark/no lights	Number of vehicles...2
Crossing(human)....No Human control within 50m	Number of casualties.2
Crossing(physical)..No crossing facility within 50m	Surface.....Dry

**Did a police officer attend?**  
Yes

**Accident Description**

Veh 1 (Car), turning left from Northwest to Northeast; Veh 2 (Goods Vehicle >= 7.5T), Going ahead Other from Northeast to Southwest.

**2 Vehicles**

Vehicle number.....1	First impact.....Front
Other vehicle.....2	Hit object in c'way..None
Vehicle class.....Car	Hit object off c'way.None
Junction location...Entering main road	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Female
Direction.....North west North east	Driver age.....76
Manoeuvres.....Turning left	
Skidding.....No	Hit and Run.....No
Left c'way.....Did not leave c'way	Breath test.....Negative
Towing.....No	Journey purpose.....Other
Foreign vehicle....Not foreign	

Vehicle number.....2	First impact.....Offside
Other vehicle.....1	Hit object in c'way..None
Vehicle class.....Goods > 7.5t	Hit object off c'way.None
Junction location...Mid junction	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Male
Direction.....North east South west	Driver age.....45
Manoeuvres.....Going ahead other	
Skidding.....No	Hit and Run.....No
Left c'way.....Did not leave c'way	Breath test.....Negative
Towing.....Articulated veh.	Journey purpose.....Journey as part of work
Foreign vehicle....Not foreign	

**2 Casualties**

Casualty number.....1	Car passenger.....Not a passenger
Casualty class.....Driver or Rider	PSV passenger.....Not a passenger
Gender.....Female	Seat belt usage.....
Age.....76	School pupil.....Other
	School .....
Severity.....Slight	Pedestrian location..
Vehicle no.....1	Pedestrian movement..
Ped Direction.....	Roadworker injured...
Casualty number.....2	Car passenger.....Front seat passenger
Casualty class.....Passenger	PSV passenger.....Not a passenger
Gender.....Female	Seat belt usage.....
Age.....18	School pupil.....Other
	School .....
Severity.....Slight	Pedestrian location..
Vehicle no.....1	Pedestrian movement..
Ped Direction.....	Roadworker injured...

Accident Date BETWEEN '01-Jul-2007' AND '30-Jun-2012'

Accident Reference: 42128

Fatal

Accident 115 of 119

Date & time.....Thursday 05/07/2007 19:25  
 Grid reference.....607688/297453  
 District.....Breckland  
 Primary road.....A11  
 Secondary road.....  
 Weather.....Rain  
 Lighting.....Daylight  
 Crossing(human).....No Human control within 50m  
 Crossing(physical)..No crossing facility within 50m

Speed limit.....70 Mph  
 Road type.....Dual c'way  
 Junction detail.....Not at or within 20m of junction  
 Junction control.....  
 Special conditions...None  
 Carriageway hazards..None  
 Number of vehicles...1  
 Number of casualties..2  
 Surface.....Wet

**Did a police  
 officer  
 attend?**

**Accident Description**

Veh 1 (Car), Going ahead Other from Southwest to Northeast. Collision Diagram Info: Losing Control - Collision with Object or Street Furniture

**1 Vehicle**

Vehicle number.....1  
 Other vehicle.....0  
 Vehicle class.....Car  
 Junction location...Not at junction  
 Restricted location..On main carriageway  
 Direction.....South west North east  
 Manoeuvres.....Going ahead other  
 Skidding.....Yes  
 Left c'way.....Left c'way near-side  
 Towing.....No  
 Foreign vehicle.....Not foreign

First impact.....Front  
 Hit object in c'way..None  
 Hit object off c'way..Road sign or signal  
 Parts damaged..... / /  
 Driver gender.....Male  
 Driver age.....34  
 Hit and Run.....No  
 Breath test.....Not requested  
 Journey purpose.....

**2 Casualties**

Casualty number.....1  
 Casualty class.....Driver or Rider  
 Gender.....Male  
 Age.....34  
 Severity.....Fatal  
 Vehicle no.....1  
 Ped Direction.....

Car passenger.....Not a passenger  
 PSV passenger.....Not a passenger  
 Seat belt usage.....  
 School pupil.....Other  
 School ..  
 Pedestrian location..  
 Pedestrian movement..  
 Roadworker injured...

Casualty number.....2  
 Casualty class.....Passenger  
 Gender.....Male  
 Age.....28  
 Severity.....Slight  
 Vehicle no.....1  
 Ped Direction.....

Car passenger.....Front seat passenger  
 PSV passenger.....Not a passenger  
 Seat belt usage.....  
 School pupil.....Other  
 School ..  
 Pedestrian location..  
 Pedestrian movement..  
 Roadworker injured...

Accident Date BETWEEN '01-Jul-2007' AND '30-Jun-2012'

Accident Reference: T080257      Slight      First Road: A11      Accident 116 of 119

Date & time.....Tuesday 23/12/2008 15:20	Speed limit.....70 Mph
Grid reference.....607740/297470	Road type.....Dual c'way
District.....Breckland	Junction detail.....Not at or within 20m of junction
Primary road.....A11	Junction control.....
Secondary road.....	Special conditions...None
Weather.....Fine	Carriageway hazards..None
Lighting.....Daylight	Number of vehicles...2
Crossing(human)....No Human control within 50m	Number of casualties.1
Crossing(physical)..No crossing facility within 50m	Surface.....Wet

**Did a police officer attend?**  
Yes

**Accident Description**

Veh 1 (Car), Going ahead Other from Northeast to Southwest; Veh 2 (Car), Going ahead Other from Northeast to Southwest. Collision Diagram Info: Tail End Collision

**2 Vehicles**

Vehicle number.....1	First impact.....Front
Other vehicle.....2	Hit object in c'way..None
Vehicle class.....Car	Hit object off c'way.None
Junction location...Not at junction	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Female
Direction.....North east South west	Driver age.....50
Manoeuvres.....Going ahead other	
Skidding.....No	Hit and Run.....No
Left c'way.....Did not leave c'way	Breath test.....Negative
Towing.....No	Journey purpose.....Other
Foreign vehicle....Not foreign	

Vehicle number.....2	First impact.....Back
Other vehicle.....1	Hit object in c'way..None
Vehicle class.....Car	Hit object off c'way.None
Junction location...Not at junction	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Not known
Direction.....North east South west	Driver age.....-1
Manoeuvres.....Going ahead other	
Skidding.....No	Hit and Run.....No
Left c'way.....Did not leave c'way	Breath test.....Negative
Towing.....No	Journey purpose.....Other
Foreign vehicle....Not foreign	

**1 Casualty**

Casualty number.....1	Car passenger.....Front seat passenger
Casualty class.....Passenger	PSV passenger.....Not a passenger
Gender.....Male	Seat belt usage.....
Age.....19	School pupil.....Other
	School .....
Severity.....Slight	Pedestrian location..
Vehicle no.....1	Pedestrian movement..
Ped Direction.....	Roadworker injured...

Accident Reference: T080023      Slight

Accident 117 of 119

Date & time.....Thursday 24/01/2008 19:55	Speed limit.....70 Mph
Grid reference.....607791/297518	Road type.....Dual c'way
District.....Breckland	Junction detail.....Not at or within 20m of junction
Primary road.....A11	Junction control.....
Secondary road.....	Special conditions...None
Weather.....Fine	Carriageway hazards..None
Lighting.....Dark/no lights	Number of vehicles...2
Crossing(human)....No Human control within 50m	Number of casualties..2
Crossing(physical)..No crossing facility within 50m	Surface.....Dry

**Did a police officer attend?**  
Yes

**Accident Description**

Veh 1 (Car), Going ahead Other from Southwest to Northeast; Veh 2 (Car), Going ahead Other from Southwest to Northeast. Collision Diagram Info: Tail End Collision

**2 Vehicles**

Vehicle number.....1	First impact.....Front
Other vehicle.....2	Hit object in c'way..None
Vehicle class.....Car	Hit object off c'way..None
Junction location...Not at junction	Parts damaged..... / /
Restricted location..On main carriageway	Driver gender.....Male
Direction.....South west North east	Driver age.....33
Manoeuvres.....Going ahead other	
Skidding.....Overturned	
Left c'way.....Left c'way offside onto central res.	Hit and Run.....No
Towed.....No	Breath test.....Positive
Foreign vehicle....Not foreign	Journey purpose.....

Vehicle number.....2	First impact.....Back
Other vehicle.....1	Hit object in c'way..None
Vehicle class.....Car	Hit object off c'way..None
Junction location...Not at junction	Parts damaged..... / /
Restricted location..On main carriageway	Driver gender.....Male
Direction.....South west North east	Driver age.....47
Manoeuvres.....Going ahead other	
Skidding.....No	
Left c'way.....Did not leave c'way	Hit and Run.....No
Towing.....No	Breath test.....Negative
Foreign vehicle....Not foreign	Journey purpose.....

**2 Casualties**

Casualty number.....1	Car passenger.....Not a passenger
Casualty class.....Driver or Rider	PSV passenger.....Not a passenger
Gender.....Male	Seat belt usage.....
Age.....33	School pupil.....Other
	School .....
Severity.....Slight	Pedestrian location..
Vehicle no.....1	Pedestrian movement..
Ped Direction.....	Roadworker injured...
Casualty number.....2	Car passenger.....Front seat passenger
Casualty class.....Passenger	PSV passenger.....Not a passenger
Gender.....Male	Seat belt usage.....
Age.....30	School pupil.....Other
	School .....
Severity.....Slight	Pedestrian location..
Vehicle no.....1	Pedestrian movement..
Ped Direction.....	Roadworker injured...

Accident Date BETWEEN '01-Jul-2007' AND '30-Jun-2012'

Accident Reference: 0059618      Slight      Bunwell Road First Road: C139      Accident 118 of 119

Date & time.....Sunday 09/01/2011 08:45	Speed limit.....60 Mph
Grid reference.....607892/295566	Road type.....Single c'way
District.....Breckland	Junction detail.....Not at or within 20m of junction
Primary road.....C139	Junction control.....
Secondary road.....	Special conditions...None
Weather.....Other	Carriageway hazards..None
Lighting.....Daylight	Number of vehicles...2
Crossing(human).....No Human control within 50m	Number of casualties.1
Crossing(physical)..No crossing facility within 50m	Surface.....Ice

**Did a police officer attend?**  
No - reported over the counter

**Accident Description**

Veh 1 (Car), Going ahead left Hand Bend from Southeast to Southwest; Veh 2 (Car), Going ahead right Hand Bend from Southwest to Southeast.

**2 Vehicles**

Vehicle number.....1	First impact.....Front
Other vehicle.....2	Hit object in c'way..None
Vehicle class.....Car	Hit object off c'way.None
Junction location...Not at junction	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Male
Direction.....South east South west	Driver age.....22
Manoeuvres.....Going ahead left hand bend	
Skidding.....Yes	Hit and Run.....No
Left c'way.....Did not leave c'way	Breath test.....Not requested
Towing.....No	Journey purpose.....Other
Foreign vehicle.....Not foreign	

Vehicle number.....2	First impact.....Front
Other vehicle.....1	Hit object in c'way..None
Vehicle class.....Car	Hit object off c'way.None
Junction location...Not at junction	Parts damaged..... / /
Restricted location.On main carriageway	Driver gender.....Male
Direction.....South west South east	Driver age.....22
Manoeuvres.....Going ahead right hand bend	
Skidding.....Yes	Hit and Run.....No
Left c'way.....Did not leave c'way	Breath test.....Not requested
Towing.....No	Journey purpose.....Other
Foreign vehicle.....Not foreign	

**1 Casualty**

Casualty number.....1	Car passenger.....Not a passenger
Casualty class.....Driver or Rider	PSV passenger.....Not a passenger
Gender.....Male	Seat belt usage.....
Age.....22	School pupil.....Other
	School .....
Severity.....Slight	Pedestrian location..
Vehicle no.....2	Pedestrian movement..
Ped Direction.....	Roadworker injured...





Reference Number	Date / Day	Month	Year	Time	Vehicle	Casualty / Age	Failed to Give-Way	Loss of Control	Hit Object IN C'way	Hit Object OEF C'way	Vehicle Left C'way	Breath Test	Contributory Factors	Severity	Dark / Lit	Weather Conditions	Road Surface	Special Conditions	Carriageway Hazards	Vehicle Manoeuvres
4628	Sd23	Feb	2008	0915	Vehicle	2								4						
4372	Sd20	Feb	2008	0915	Vehicle	2								4						
T110	We17	Aug	2011	1340	Vehicle	3								4						
0053	Sd17	Oct	2009	2308	Vehicle	4								4						
0032	Mo22	Jun	2009	1030	Vehicle	5								4						
0060	Tu05	Apr	2010	1200	Vehicle	5								4						
T100	Th10	Jul	2010	0030	Vehicle	5								4						
0064	We25	Jan	2010	1858	Vehicle	5								4						
4277	Sd18	Aug	2011	1125	Vehicle	5								4						
4799	Tu05	Jul	2008	1138	Vehicle	5								4						
4906	Fr04	Jul	2008	0907	Vehicle	5								4						
0058	Th23	Sep	2010	1720	Vehicle	5								4						
0032	Fr05	Jun	2009	1555	Vehicle	5								4						
0062	We31	Oct	2011	1830	Vehicle	5								4						
0065	Sd24	Mar	2012	2100	Vehicle	5								4						
4244	Tu24	Jul	2007	1713	Vehicle	5								4						
4276	Tu07	Aug	2007	1840	Vehicle	5								4						
To70	Mo07	Oct	2011	1440	Vehicle	5								4						
0060	Th31	Mar	2011	1135	Vehicle	5								4						
0060	Fr25	Mar	2011	1135	Vehicle	5								4						

Reference Number	Date / Day	Month	Year	Time	Vehicle	Casualty / Age	Failed to Give-Way	Loss of Control	Hit Object IN C'way	Hit Object OEF C'way	Vehicle Left C'way	Breath Test	Contributory Factors	Severity	Dark / Lit	Weather Conditions	Road Surface	Special Conditions	Carriageway Hazards	Vehicle Manoeuvres
0062	We31	Aug	2011	1925	Vehicle	5								4						
0056	Su23	May	2010	1545	Vehicle	5								4						
0059	Th20	Jan	2011	0819	Vehicle	5								4						
0062	Th22	Sep	2011	1036	Vehicle	5								4						
0066	Th19	Jun	2012	1121	Vehicle	5								4						
0052	Th18	Jun	2009	2226	Vehicle	5								4						
0059	Mo22	Nov	2010	1900	Vehicle	5								4						
0063	Mo24	Nov	2010	2130	Vehicle	5								4						
0054	Sd24	Oct	2009	0915	Vehicle	5								4						
4700	Fr04	Jun	2008	1736	Vehicle	5								4						
T100	Fr04	Jun	2008	2215	Vehicle	5								4						
4695	Th22	May	2008	1307	Vehicle	5								4						
0065	Mo24	Apr	2011	1150	Vehicle	5								4						
0063	Mo24	Oct	2011	1150	Vehicle	5								4						
0050	Th01	Jan	2009	0356	Vehicle	5								4						
T100	Fr12	May	2010	1555	Vehicle	5								4						
0056	Fr21	May	2010	0519	Vehicle	5								4						
0057	Su27	Jun	2010	2252	Vehicle	5								4						
0054	Tu10	Nov	2009	1744	Vehicle	5								4						
0052	Su31	May	2010	1100	Vehicle	5								4						

Reference Number	Date / Day	Month	Year	Time	Vehicle	Casualty / Age	Failed to Give-Way	Loss of Control	Hit Object IN C'way	Hit Object OEF C'way	Vehicle Left C'way	Breath Test	Contributory Factors	Severity	Dark / Lit	Weather Conditions	Road Surface	Special Conditions	Carriageway Hazards	Vehicle Manoeuvres
4618	Fr21	Mar	2008	0200	Vehicle	5								4						
0061	Fr23	May	2011	1045	Vehicle	5								4						
T100	Mo12	Jul	2011	1913	Vehicle	5								4						
0060	Mo11	Apr	2011	0942	Vehicle	5								4						
4807	Tu12	Aug	2008	1830	Vehicle	5								4						
0064	Fr06	Jan	2012	2225	Vehicle	5								4						
0064	Fr06	Jan	2012	2225	Vehicle	5								4						
0066	Fr22	Dec	2009	1730	Vehicle	5								4						
T120	We22	Jun	2012	2139	Vehicle	5								4						
0059	Fr26	Nov	2010	2004	Vehicle	5								4						
4501	Tu08	Jan	2008	2003	Vehicle	5								4						
0058	Su14	Jul	2010	0645	Vehicle	5								4						
4247	Sd21	Jul	2007	0645	Vehicle	5								4						
4256	Mo30	Jul	2009	1749	Vehicle	5								4						
0052	Su05	Jul	2009	1805	Vehicle	5								4						
0050	Sd22	Jun	2008	1805	Vehicle	5								4						
0059	Su02	Jan	2011	1810	Vehicle	5								4						
0053	Su04	Oct	2009	1253	Vehicle	5								4						


Reference Number	Date / Day	Month	Year	Time	Vehicle	Casualty / Age	Failed to Give-Way	Loss of Control	Hit Object IN C'way	Hit Object OEF C'way	Vehicle Left C'way	Breath Test	Contributory Factors	Severity	Dark / Lit	Weather Conditions	Road Surface	Special Conditions	Carriageway Hazards	Vehicle Manoeuvres
4817	Fr22	Aug	2008	1500	Vehicle	5								4						
4555	Sd16	Feb	2008	1125	Vehicle	5								4						
0066	Fr15	Jun	2012	0845	Vehicle	5								4						
0050	Tu30	Dec	2008	1255	Vehicle	5								4						
0062	Fr22	Jul	2011	1700	Vehicle	5								4						
4873	We24	Sep	2011	1749	Vehicle	5								4						
0062	Fr16	Sep	2011	0900	Vehicle	5								4						
0059	Th16	Dec	2010	1630	Vehicle	5								4						
0064	Fr13	Jan	2012	1650	Vehicle	5								4						
0050	Fr27	Feb	2009	1525	Vehicle	5								4						
4907	Th23	Oct	2011	1045	Vehicle	5								4						
0058	Fr24	Sep	2011	1145	Vehicle	5								4						
0056	We28	Apr	2010	1245	Vehicle	5								4						
0057	Tu06	Jul	2010	1130	Vehicle	5								4						
0058	Mo03	Oct	2011	0535	Vehicle	5								4						
0056	Su04	Apr	2010	2024	Vehicle	5								4						
T100	Mo15	Feb	2010	1530	Vehicle	5								4						
To70	Sd08	Dec	2011	1630	Vehicle	5								4						
0063	Mo24	Nov	2011	1005	Vehicle	5								4						

Reference Number	Date / Day	Month	Year	Time	Vehicle	Casualty / Age	Failed to Give-Way	Loss of Control	Hit Object IN C'way	Hit Object OEF C'way	Vehicle Left C'way	Breath Test	Contributory Factors	Severity	Dark / Lit	Weather Conditions	Road Surface	Special Conditions	Carriageway Hazards	Vehicle Manoeuvres
0057	Tu13	Jul	2010	1530	Vehicle	5								4						
0052	Fr29	May	2009	0850	Vehicle	5								4						
0065	Sd28	Apr	2012	0630	Vehicle	5								4						
0063	We19	Oct	2011	1505	Vehicle	5								4						
4858	We17	Sep	2012	1202	Vehicle	5								4						
4292	Mo27	Aug	2007	1303	Vehicle	5								4						
4875	Mo29	Aug	2008	1610	Vehicle	5								4						
0063	Th17	Nov	2011	0827	Vehicle	5								4						
0057	Su11	Jul	2010	1315	Vehicle	5								4						
To70	Sd01	Nov	2007	0820	Vehicle	5								4						
0054	Tu24	Nov	2009	0744	Vehicle	5								4						
0055	Su14	Mar	2011	1129	Vehicle	5								4						
0062	Sd30	Jul	2011	1340	Vehicle	5								4						
0060	Su27	Feb	2011	1130	Vehicle	5								4						
4570	Fr29	Feb	2008	1232	Vehicle	5								4						
0052	Mo06	Jun	2010	1510	Vehicle	5								4						
To80	Su11	May	2008	2149	Vehicle	5								4						
We30	Mo15	Sep	2009	2149	Vehicle	5								4						
Sd15	Aug	2011	1108	1850	Vehicle	5								4						
0051	Tu26																			


# Stick Diagrams

## — general key

Reference Number	Date / Day / Month / Year / Time	Severity	Dark / Lit	Weather Conditions	Road Surface	Special Conditions	Carriageway Hazards	Vehicle Manoeuvres	Casualty /age	Breath Test	Contributory Factor 1/2	Contributory Factor 3/4	School No./Ref.
99CC 0151	Wed 19 Feb 92 0900	Se	Se					Vehicle 1: 5 t Vehicle 2: 6 t Vehicle 3: 7 c Vehicle 4: 8			24	24	321
00CC 0326	Thu 16 Apr 92 1405	S1	S1									220	220
98CC 0413	Wed 20 May 99 1901	S1	S1								27	27	331



Reference Number	Date / Day / Month / Year / Time	Severity	Dark / Lit	Weather Conditions	Road Surface	Special Conditions	Carriageway Hazards	Vehicle Manoeuvres	Casualty /age	Breath Test	Contributory Factor 1/2	Contributory Factor 3/4	School No./Ref.
96EE 0071	Tue 27 Feb 96 2130	S1	S1					Vehicle 1: 5 t Vehicle 2: 6 t Vehicle 3: 7 c Vehicle 4: 8			36	36	0621
96EE 0097	Fri 15 Mar 96 1035	Se	Se									321	321
96EE 0152	Wed 24 Apr 96 0800	S1	S1								81	81	321



### REFERENCE

98 = YEAR OF ACCIDENT  
CC = DIVISION CODE  
0413 = ACCIDENT NUMBER

DAY, DATE, MONTH, YEAR

TIME OF ACCIDENT (24HR Clock)

### SEVERITY

S1 SLIGHT INJURY  
Se SERIOUS INJURY  
Fa FATAL INJURY

### LIGHT CONDITIONS

Dark with street lights  
Dark without street lights  
Daylight

### WEATHER CONDITIONS

Fog  
Rain  
Snow  
High Wind/Rain

### ROAD CONDITIONS

Road Defect  
Wet/Damp  
Snow  
Ice/Frost

Vehicle Overtaken  
Vehicle Lost Control

### OBJECTS STRUCK

Vehicle Struck Kerb  
Vehicle Struck Lamp  
Vehicle Struck Barrier  
Vehicle Entered Ditch

### MANOEUVRES

Vehicle Loss of Control  
Stationary Vehicle  
Vehicle Turning Left  
Rear Shunt  
Single Vehicle  
"U" Turn  
Vehicle Striking Pedestrian  
Vehicle Striking Masked Pedestrian  
Parked Vehicle

### VEHICLES

Motor Cycle with Age of Rider  
Car with Age of Driver  
HGV with Age of Driver  
LGV with Age of Driver  
P/C with Age of Driver  
PSV with Age of Driver  
Pedestrian (from offside)

### CASUALTY

Driver with Age  
Passenger with Age  
Pedestrian with Age (reduced agility)  
Pedestrian with Age  
Pedestrian with Age (child)


NOTE sections below Casualty/Age may not be included on all printouts.

NB this key is not exhaustive but covers the majority of the symbols found on the majority of printouts. If you find symbols not covered by this key or would like to discuss this information please contact the engineer who issued this drawing.

SCHEME				KEY TO ACCIDENT DATA AND STICK DIAGRAMS			
TITLE							
Scale	Date	Drawn	Approved	Dwg.No.			
N.T.S.							

## Appendix K – Listed Buildings in Attleborough

# Listed Buildings in Attleborough Town Centre



## Heritage Listed Buildings in Attleborough

Reference	Name of Listed Building	Description
1	Church Of The Assumption (Church of St Mary), Church Street (south side)	Grade I
2	Stebbings Ironmongers and Cockings Limited, Church Street (south side)	Grade II
3	The Griffin Hotel, Church Street (south side)	Grade II
4	Homestead, Connaught Road (north side)	Grade II
5	The Thatched Cottage, Connaught Road	Grade II
6	Grange Farmhouse, Deopham Road	Grade II
7	Dovecote 30 Metres East Of Attleborough Lodge, Ellingham Road	Grade II
8	Barn 15 Metres North East Of Potmere Farmhouse, Haverscroft Street	Grade II
9	Barn 25 Metres North East Of Potmere Farmhouse, Haverscroft Street	Grade II
10	Potmere Farmhouse, Haverscroft Street	Grade II
11	F And T King (Antiques), High Street (north side)	Grade II
12	Pillar, Junction Of Station Road	Grade II
13	White Lodge Inn, London Road	Grade II
14	1 And 2 Prospect Avenue (west side)	Grade II
15	Bank Cottage, 1 Queens Square (north side)	Grade II
16	A E Bush, Queens Square (north side)	Grade II
17	Cyprus House, Queens Square (west side)	Grade II
18	The Doric Restaurant, Queens Square (north side)	Grade II
19	Village Pump, Queens Square	Grade II
20	White House, Queens Square (north side)	Grade II
21	Lushers Cottage, Whitehorse Lane	Grade II
22	Attleborough Hall, Wymondham Road	Grade II*
23	Moat Wall At Attleborough Hall, Wymondham Road	Grade II*
24	Barn 25 Metres South East Of West Farmhouse, Carvers Lane	Grade II
25	Borough Farmhouse	Grade II
26	Corner Farmhouse	Grade II
27	Cottage 50 Metres North North East Of Attleborough Hall	Grade II
28	West Farmhouse, Carvers Lane	Grade II

There are three types of listed status for buildings in England and Wales:

- Grade I: buildings of exceptional interest
- Grade II\*: particularly important buildings of more than special interest
- Grade II: buildings that are of special interest, warranting every effort to preserve them

1. Church Of The Assumption (Church of St Mary), Church Street (south side)



3. The Griffin Hotel, Church Street (south side)



2. Stebbings Ironmongers and Cockings Limited, Church Street (south side)



4. The Homestead, Connaught Road (north side)



5. The Thatched Cottage, Connaught Road (south side)



7. Dovecote 30 Metres East Of Attleborough Lodge, Ellingham Road



6. Grange Farmhouse, Deopham Road



8. Barn 15 Metres North East Of Potmere Farmhouse, Haverscroft Street



9. Barn 25 Metres North East Of Potmere Farmhouse, Haverscroft Street



11. F And T King (Antiques), High Street (north side)



10. Potmere Farmhouse, Haverscroft Street



12. Pillar, Junction Of Station Road



13. White Lodge Inn, London Road



15. Bank Cottage, 1 Queens Square (north side)



14. 1 And 2 Prospect Avenue (west side)



16. A E Bush, Queens Square (north side)



17. Cyprus House, Queens Square (west side)



19. Village Pump, Queens Square



18. The Doric Restaurant, Queens Square (north side)



20. White House, Queens Square (north side)



21. Lushers Cottage, Whitehorse Lane



23. Moat Wall At Attleborough Hall, Wymondham Road



22. Attleborough Hall, Wymondham Road



24. Barn 25 Metres South East Of West Farmhouse, Carvers Lane



25. Borough Farmhouse



27. Cottage 50 Metres North East Of Attleborough Hall




26. Corner Farmhouse



28. West Farmhouse, Carvers Lane



## Appendix L – Zone Structure





## Appendix M – Calibration Results

**Attleborough Transport Study**  
PARAMICS MODELS - AM CALIBRATION RESULTS

Junction	Movement	A Node	B Node	C Node	D Node	Observed	Modelled	Diff	% Diff	GEH	Within 15%	Within 25%	Within 50%	GEH 5.0	GEH 7.0	GEH 10.0	
Church Street / Exchange Street / Queens Road	Church Street Straight on	1	0	0	8	793	767	-26	-3%	0.9	OK	OK	OK	OK	OK	OK	
	Town Centre Car Park Left turn to Church Street	5	0	0	8	171	145	-26	-15%	2.1	OK	OK	OK	OK	OK	OK	
	Queens Road to Church Street	341	1	1	0	211	186	-25	-12%	1.8	OK	OK	OK	OK	OK	OK	
	Queens Road to Town Centre Carpark	340	2	2	192	183	252	69	38%	4.7	OK	OK	OK	OK	OK	OK	
	Exchange Street Straight on to Church Street	45	3	3	339	901	765	-136	-15%	4.7	Failed	OK	OK	OK	OK	OK	
	Exchange Street left turn to Queens Road	45	3	3	340	282	252	-31	-11%	1.9	OK	OK	OK	OK	OK	OK	
Norwich Road / Besthorpe Road / Surrogate Street / Church Street	Church Street straight on to Besthorpe Road	9	10	10	13	117	103	-15	-13%	1.4	OK	OK	OK	OK	OK	OK	
	Church Street right turn to Connaught Road	9	10	10	12	522	443	-79	-15%	3.6	OK	OK	OK	OK	OK	OK	
	Norwich Road left turn to Besthorpe Road	11	10	10	13	14	12	-2	-13%	0.5	OK	OK	OK	OK	OK	OK	
	Norwich Road straight on to Surrogate Street	11	10	10	12	401	468	67	17%	3.2	OK	OK	OK	OK	OK	OK	
	Church Street left to Norwich Road	9	11	11	70	329	368	39	12%	2.1	OK	OK	OK	OK	OK	OK	
	Norwich Road to start of Surrogate Street	70	11	11	10	416	481	65	16%	3.1	OK	OK	OK	OK	OK	OK	
Surrogate Street / Theives Lane / Station Road / Connaught Road	Besthorpe Road left turn to Surrogate Street	13	12	12	288	44	44	0	0%	0.0	OK	OK	OK	OK	OK	OK	
	Surrogate Street left turn to Thieves Lane	288	19	19	170	23	24	0	0%	0.0	OK	OK	OK	OK	OK	OK	
	Surrogate Street to Station Road	288	19	19	21	428	513	85	20%	3.9	OK	OK	OK	OK	OK	OK	
	Surrogate Street to Connaught Road	288	19	19	20	516	417	-99	-19%	4.6	OK	OK	OK	OK	OK	OK	
	Thieves Lane to Station Road	170	19	19	21	138	94	-44	-32%	4.1	OK	OK	OK	OK	OK	OK	
	Thieves Lane to Connaught Road	170	19	19	20	27	48	21	79%	3.5	OK	OK	OK	OK	OK	OK	
Exchange Street / Connaught Road / High Street	Station Road left turn to Connaught Road	21	20	20	53	345	396	51	15%	2.6	OK	OK	OK	OK	OK	OK	
	High Street straight on to Exchange Street	47	156	156	46	520	505	-14	-3%	0.6	OK	OK	OK	OK	OK	OK	
	Connaught Road right turn to Exchange Street	155	156	156	46	566	509	-57	-10%	2.4	OK	OK	OK	OK	OK	OK	
Norwich Road / A11 Off-slip	Connaught Road to High Street	155	47	47	52	345	324	-22	-6%	1.2	OK	OK	OK	OK	OK	OK	
	Norwich Road straight on to Norwich Road over A11	191z	72	72	269	303	344	41	14%	2.3	OK	OK	OK	OK	OK	OK	
	Norwich Road straight on to Norwich Road from over A11	269	72	72	191z	141	142	1	0%	0.1	OK	OK	OK	OK	OK	OK	
	A11 off-slip right turn to Norwich Road over A11	271	72	72	269	6	7	1	11%	0.3	OK	OK	OK	OK	OK	OK	
Norwich Road / Norwich Road	A11 off-slip left turn to Norwich Road	271	72	72	191z	240	282	42	18%	2.6	OK	OK	OK	OK	OK	OK	
	Norwich Road straight on to A11 on-slip	75	74	74	268	227	231	4	2%	0.3	OK	OK	OK	OK	OK	OK	
	Norwich Road left turn to Norwich Road	75	74	74	76	83	120	37	45%	3.7	OK	OK	OK	OK	OK	OK	
	Norwich Road right turn to A11 on slip	76	74	74	268	12	19	7	53%	1.7	OK	OK	OK	OK	OK	OK	
A11 On-slip / Blackthorn Road	Norwich Road right turn to Norwich Road over A11	76	74	74	75	141	142	1	1%	0.1	OK	OK	OK	OK	OK	OK	
	Blackthorn Road right turn to A11 on-slip	298	80	80	296	133	85	-48	-36%	4.6	OK	OK	OK	OK	OK	OK	
	Blackthorn Road left turn to A11 on-slip	298	80	80	299	100	18	-82	-82%	10.7	OK	OK	OK	Failed	Failed	Failed	
	All on-slip left turn to Blackthorn Road	296	80	80	298	27	10	-17	-62%	3.9	OK	OK	OK	OK	OK	OK	
A11 / B1077	A11 on-slip straight on to A11 on-slip	296	80	80	299	102	115	13	13%	1.2	OK	OK	OK	OK	OK	OK	
	A11 on-slip left turn to B1077 Queens Road	296	295	295	84	40	36	-4	-10%	0.6	OK	OK	OK	OK	OK	OK	
	A11 on-slip left turn to B1077 Northbound	296	295	295	168	93	49	-44	-47%	5.2	OK	OK	OK	Failed	OK	OK	
	B1077 Queens Road left turn to A11 on-slip	165	84	84	296	35	22	-13	-37%	2.4	OK	OK	OK	OK	OK	OK	
	B1077 Queens Road straight on to B1077 northbound	165	84	84	295	258	286	28	11%	1.7	OK	OK	OK	OK	OK	OK	
	A11 off-slip left turn to B1077 Queens Road	166	165	165	78	35	26	-8	-24%	1.5	OK	OK	OK	OK	OK	OK	
	A11 off-slip straight on to A11 on-slip	166	84	84	296	16	19	2	14%	0.5	OK	OK	OK	OK	OK	OK	
	A11 off-slip right turn to B1077 Northbound	166	84	84	295	61	88	27	44%	3.1	OK	OK	OK	OK	OK	OK	
	B1077 southbound straight on to B1077 Queens Road	295	84	84	165	210	250	40	19%	2.6	OK	OK	OK	OK	OK	OK	
	B1077 southbound right turn to A11 on-slip	295	84	84	296	78	84	6	8%	0.7	OK	OK	OK	OK	OK	OK	
	A11 on-slip left turn to B1077 southbound	264	265	265	168	27	23	-3	-12%	0.7	OK	OK	OK	OK	OK	OK	
	A11 off-slip right turn to B1077 southbound	163	85	85	265	27	52	25	95%	4.0	OK	OK	OK	OK	OK	OK	
	A11 off-slip left turn to B1077 Ellingham Road	163	164	164	86	9	14	5	56%	1.5	OK	OK	OK	OK	OK	OK	
	A11 off-slip straight on to A11 on-slip	163	85	85	264	6	10	4	58%	1.3	OK	OK	OK	OK	OK	OK	
	B1077 Ellingham Road left turn to A11 on-slip	164	85	85	264	139	151	12	8%	1.0	OK	OK	OK	OK	OK	OK	
	B1077 Ellingham Road straight on to B1077 southbound	164	85	85	265	235	200	-35	-15%	2.4	OK	OK	OK	OK	OK	OK	
A11 On-slip / Deopham Road	B1077 northbound right turn to A11 on-slip	265	85	85	264	164	187	23	14%	1.7	OK	OK	OK	OK	OK	OK	
	B1077 northbound straight on to B1077 Ellingham Road	265	85	85	164	256	237	-19	-7%	1.2	OK	OK	OK	OK	OK	OK	
	A11 on-slip straight on to A11 on-slip	264	88	88	263	270	325	55	21%	3.2	OK	OK	OK	OK	OK	OK	
	A11 on-slip left turn to Deopham Road	264	88	88	89	35	23	-12	-35%	2.3	OK	OK	OK	OK	OK	OK	
A11 Roundabout South of Attleborough	Deopham Road left turn to A11 on-slip	89	88	88	263	4	5	1	32%	0.6	OK	OK	OK	OK	OK	OK	
	Deopham Road right turn to A11 on-slip	89	88	88	264	27	23	-3	-12%	0.6	OK	OK	OK	OK	OK	OK	
	London Road Approach to Roundabout	246	245	245	151	214	238	24	11%	1.6	OK	OK	OK	OK	OK	OK	
	All East bound approach to Roundabout	242	122c	122c	122d	1175	1218	44	4%	1.3	OK	OK	OK	OK	OK	OK	
Screen Lines	Side Roundabout Approach to roundabout	56	243	243	122a	80	78	-2	-2%	0.2	OK	OK	OK	OK	OK	OK	
	A11 Westbound Approach to Roundabout	248	150	150	122b	1011	1145	134	13%	4.1	OK	OK	OK	OK	OK	OK	
	<b>Screen Lines</b>																
	Norwich Road Eastbound	11	70			329	368	39	12%	2.1	OK	OK	OK	OK	OK	OK	
	Norwich Road Westbound	70	11			416	481	65	16%	3.1	OK	OK	OK	OK	OK	OK	
	B1077 Station Road Northbound	22	21			345	396	51	15%	2.6	OK	OK	OK	OK	OK	OK	
	B1077 Station Road Southbound	19	21	21	22	566	605	39	7%	1.6	OK	OK	OK	OK	OK	OK	
	High Street Eastbound	52	47			520	505	-14	-3%	0.6	OK	OK	OK	OK	OK	OK	
	High Street Westbound	47	52			345	324	-22	-6%	1.2	OK	OK	OK	OK	OK	OK	
	Queens Road Southbound	2	341	341	1	211	223	11	5%	0.8	OK	OK	OK	OK	OK	OK	
Queens Road Northbound	2	192			282	252	-31	-11%	1.9	OK	OK	OK	OK	OK	OK		
Surrogate Street	12	288	288	19	923	955	31	3%	1.0	OK	OK	OK	OK	OK	OK		

FAILED	1	0	0	2	1	1
OK	58	59	59	57	58	58
%	98%	100%	100%	97%	98%	98%

**Attleborough Transport Study**  
PARAMICS MODELS - PM CALIBRATION RESULTS

Junction	Year	Movement	A Node	B Node	C Node	D Node	Observed	Modelled Light	Modelled Heavy	Modelled	Diff	% Diff	GEH	Within 15%	Within 25%	Within 50%	GEH 5.0	GEH 7.0	GEH 10.0
Church Street / Exchange Street / Queens Road	2003	Church Street Straight on	1	0	0	8	873	779	7	785	-87	-10%	3.0	OK	OK	OK	OK	OK	OK
	2003	Town Centre Car Park Left turn to Church Street	5	0	0	8	219	146	3	149	-69	-32%	5.1	OK	OK	OK	Failed	OK	OK
	2003	Queens Road to Church Street	341	1	1	0	243	217	3	220	-24	-10%	1.6	OK	OK	OK	OK	OK	OK
	2003	Queens Road to Town Centre Carpark	340	2	2	192	310	265	16	281	-29	-9%	1.7	OK	OK	OK	OK	OK	OK
	2003	Exchange Street Straight on to Church Street	45	3	3	339	772	692	4	696	-76	-10%	2.8	OK	OK	OK	OK	OK	OK
Norwich Road / Besthorpe Road / Surrogate Street / Church Street	2003	Exchange Street left turn to Queens Road	45	3	3	340	310	265	16	281	-29	-9%	1.7	OK	OK	OK	OK	OK	OK
	2003	Church Street straight on to Besthorpe Road	9	10	10	13	122	109	0	109	-13	-11%	1.2	OK	OK	OK	OK	OK	OK
	2003	Church Street right turn to Connaught Road	9	10	10	12	611	458	6	464	-148	-24%	6.4	Failed	OK	OK	Failed	OK	OK
	2003	Norwich Road left turn to Besthorpe Road	11	10	10	13	8	6	0	6	-2	-22%	0.7	OK	OK	OK	OK	OK	OK
	2003	Norwich Road straight on to Surrogate Street	11	10	10	12	469	436	7	443	-26	-6%	1.2	OK	OK	OK	OK	OK	OK
	2003	Church Street left to Norwich Road	9	11	11	70	354	357	4	361	7	2%	0.4	OK	OK	OK	OK	OK	OK
	2003	Norwich Road to start of Surrogate Street	70	11	11	10	477	442	7	449	-28	-6%	1.3	OK	OK	OK	OK	OK	OK
Surrogate Street / Theives Lane / Station Road / Connaught Road	2003	Besthorpe Road left turn to Surrogate Street	13	12	12	288	18	21	0	21	3	19%	0.7	OK	OK	OK	OK	OK	OK
	2003	Surrogate Street left turn to Thieves Lane	288	19	19	170	96	86	0	86	-9	-10%	1.0	OK	OK	OK	OK	OK	OK
	2003	Surrogate Street to Station Road	288	19	19	21	358	342	8	350	-8	-2%	0.4	OK	OK	OK	OK	OK	OK
	2003	Surrogate Street to Connaught Road	288	19	19	20	644	487	5	491	-153	-24%	6.4	Failed	OK	OK	Failed	OK	OK
	2008	Thieves Lane to Station Road	170	19	19	21	12	19	0	19	7	57%	1.8	OK	OK	OK	OK	OK	OK
	2008	Thieves Lane to Connaught Road	170	19	19	20	37	45	0	45	7	20%	1.2	OK	OK	OK	OK	OK	OK
Exchange Street / Connaught Road / High Street	2008	Station Road left turn to Connaught Road	21	20	20	53	517	508	17	526	9	2%	0.4	OK	OK	OK	OK	OK	OK
	2008	High Street straight on to Exchange Street	47	156	156	46	528	475	6	481	-47	-9%	2.1	OK	OK	OK	OK	OK	OK
	2008	Connaught Road right turn to Exchange Street	155	156	156	46	559	483	14	498	-61	-11%	2.7	OK	OK	OK	OK	OK	OK
Norwich Road / A11 Off-slip	2008	Connaught Road to High Street	155	47	47	52	618	549	8	556	-61	-10%	2.5	OK	OK	OK	OK	OK	OK
	2008	Norwich Road straight on to Norwich Road over A11	191z	72	72	269	354	307	5	312	-42	-12%	2.3	OK	OK	OK	OK	OK	OK
	2008	Norwich Road straight on to Norwich Road from over A11	269	72	72	191z	144	134	2	136	-9	-6%	0.7	OK	OK	OK	OK	OK	OK
	2008	A11 off-slip right turn to Norwich Road over A11	271	72	72	269	9	9	0	9	-1	-7%	0.2	OK	OK	OK	OK	OK	OK
Norwich Road / Norwich Road	2008	A11 off-slip left turn to Norwich Road	271	72	72	191z	337	315	5	320	-17	-5%	1.0	OK	OK	OK	OK	OK	OK
	2008	Norwich Road straight on to A11 on-slip	75	74	74	268	237	209	2	210	-27	-11%	1.8	OK	OK	OK	OK	OK	OK
	2008	Norwich Road left turn to Norwich Road	75	74	74	76	126	106	3	110	-16	-13%	1.5	OK	OK	OK	OK	OK	OK
	2008	Norwich Road right turn to A11 on-slip	76	74	74	268	15	14	0	14	-2	-10%	0.4	OK	OK	OK	OK	OK	OK
A11 On-slip / Blackthorn Road	2008	Norwich Road right turn to Norwich Road over A11	76	74	74	75	144	135	2	136	-8	-6%	0.7	OK	OK	OK	OK	OK	OK
	2008	Blackthorn Road right turn to A11 on-slip	298	80	80	296	84	71	0	71	-12	-15%	1.4	OK	OK	OK	OK	OK	OK
	2008	Blackthorn Road left turn to A11 on-slip	298	80	80	299	21	13	0	13	-7	-36%	1.8	OK	OK	OK	OK	OK	OK
	2008	All on-slip left turn to Blackthorn Road	296	80	80	298	103	86	0	86	-17	-17%	1.8	OK	OK	OK	OK	OK	OK
A11 / B1077	2008	A11 on-slip straight on to A11 on-slip	296	80	80	299	86	69	9	78	-8	-9%	0.8	OK	OK	OK	OK	OK	OK
	2008	A11 on-slip left turn to B1077 Queens Road	296	295	295	84	33	36	0	36	3	10%	0.6	OK	OK	OK	OK	OK	OK
	2008	A11 on-slip left turn to B1077 Northbound	296	295	295	168	51	34	0	34	-17	-34%	2.6	OK	OK	OK	OK	OK	OK
	2008	B1077 Queens Road left turn to A11 on-slip	165	84	84	296	56	43	6	49	-7	-12%	1.0	OK	OK	OK	OK	OK	OK
	2008	B1077 Queens Road straight on to B1077 northbound	165	84	84	295	346	274	9	284	-63	-18%	3.5	OK	OK	OK	OK	OK	OK
	2008	A11 off-slip left turn to B1077 Queens Road	166	165	165	78	48	13	0	13	-35	-73%	6.4	OK	OK	OK	Failed	OK	OK
	2008	A11 off-slip straight on to A11 on-slip	166	84	84	296	80	68	2	69	-11	-14%	1.3	OK	OK	OK	OK	OK	OK
	2008	A11 off-slip right turn to B1077 Northbound	166	84	84	295	97	97	2	98	1	2%	0.1	OK	OK	OK	OK	OK	OK
	2008	B1077 southbound straight on to B1077 Queens Road	295	84	84	165	256	311	9	320	64	25%	3.8	OK	OK	OK	OK	OK	OK
	2008	B1077 southbound right turn to A11 on-slip	295	84	84	296	53	43	2	45	-7	-14%	1.0	OK	OK	OK	OK	OK	OK
	2008	A11 on-slip left turn to B1077 southbound	264	265	265	168	32	34	0	34	2	8%	0.4	OK	OK	OK	OK	OK	OK
	2008	A11 off-slip right turn to B1077 southbound	163	85	85	265	37	78	4	82	45	120%	5.8	OK	OK	OK	Failed	OK	OK
	2008	A11 off-slip left turn to B1077 Ellingham Road	163	164	164	86	10	7	0	7	-3	-31%	1.1	OK	OK	OK	OK	OK	OK
	2008	A11 off-slip straight on to A11 on-slip	163	85	85	264	10	0	0	0	-10	-100%	4.5	OK	OK	OK	OK	OK	OK
	2008	B1077 Ellingham Road left turn to A11 on-slip	164	85	85	264	105	73	0	73	-32	-30%	3.4	OK	OK	OK	OK	OK	OK
	2008	B1077 Ellingham Road straight on to B1077 southbound	164	85	85	265	239	208	8	215	-24	-10%	1.6	OK	OK	OK	OK	OK	OK
2008	B1077 northbound right turn to A11 on-slip	265	85	85	264	106	104	3	107	1	1%	0.1	OK	OK	OK	OK	OK	OK	
2008	B1077 northbound straight on to B1077 Ellingham Road	265	85	85	164	390	297	8	305	-85	-22%	4.5	OK	OK	OK	OK	OK	OK	
A11 On-slip / Deopham Road	2008	A11 on-slip straight on to A11 on-slip	264	88	88	263	186	130	3	133	-52	-28%	4.1	OK	OK	OK	OK	OK	OK
	2008	A11 on-slip left turn to Deopham Road	264	88	88	89	36	48	0	48	12	34%	1.9	OK	OK	OK	OK	OK	OK
	2011	Deopham Road left turn to A11 on-slip	89	88	88	263	8	11	0	11	3	32%	0.9	OK	OK	OK	OK	OK	OK
	2011	Deopham Road right turn to A11 on-slip	89	88	88	264	33	35	0	35	2	6%	0.4	OK	OK	OK	OK	OK	OK
A11 Roundabout South of Attleborough	2011	London Road Approach to Roundabout	246	245	245	151	226	182	4	186	-40	-18%	2.8	OK	OK	OK	OK	OK	OK
	2011	All East bound approach to Roundabout	242	122c	122c	122d	1207	1116	62	1178	-30	-2%	0.9	OK	OK	OK	OK	OK	OK
	2011	Side Roundabout Approach to roundabout	56	243	243	122a	80	53	0	53	-27	-34%	3.3	OK	OK	OK	OK	OK	OK
	2011	A11 Westbound Approach to Roundabout	248	150	150	122b	959	781	47	828	-131	-14%	4.4	OK	OK	OK	OK	OK	OK
<b>Screen Line Counts</b>																			
	2011	Norwich Road Eastbound	11	70			354			361	7	2%	0.4	OK	OK	OK	OK	OK	OK
	2011	Norwich Road Westbound	70	11			477			449	-28	-6%	1.3	OK	OK	OK	OK	OK	OK
	2011	B1077 Station Road Northbound	22	21			517			526	9	2%	0.4	OK	OK	OK	OK	OK	OK
	2011	B1077 Station Road Southbound	19	21	21	22	370	362	8	370	-1	0%	0.0	OK	OK	OK	OK	OK	OK
	2011	High Street Eastbound	52	47			528			481	-47	-9%	2.1	OK	OK	OK	OK	OK	OK
	2011	High Street Westbound	47	52			618			556	-61	-10%	2.5	OK	OK	OK	OK	OK	OK
	2011	Queens Road Southbound	2	341	341	1	243	264	7	271	28	11%	1.7	OK	OK	OK	OK	OK	OK
	2011	Queens Road Northbound	2	192			310			281	-29	-9%	1.7	OK	OK	OK	OK	OK	OK
2011	Surrogate Street	12	288	288	19	1081	915	13	928	-153	-14%	4.8	OK	OK	OK	OK	OK	OK	

FAILED	2	0	0	5	0	0
OK	57	59	59	54	59	59
%	97%	100%	100%	92%	100%	100%